



Ford Mustang: N605LN

| | | | |
|-------------------------|--------------------------|-------------------------|---|
| Vinnumber: | WF0TK1EM7MMA44777 | Versionname: | Sneller rijden via Mossel Mustang Mach-E 198kW/75,7kWh RWD |
| First Registrationdate: | 18/11/2021 | Fiscalpower: | |
| Expertise Mileage: | 93573 | Power Kw: | 198 |
| Bodytype: | | Body colour: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Type of rims (mounted): | Aluminium |
| Fueltype: | Electric | Parking lot: | 479 |
| Number of seats: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Maintenance needed: | No | | |

Options

| | | |
|-----------------------|----------|----------------------|
| Number of keys total | 2 | Lining leather |
| GPS | | Rear parking sensors |
| Autom climate control | | |
| Radio multimedia | | |

Tyres

| Location | Position | Measures | Depth | Make | Type |
|----------|----------|-------------------------------------|--------|-------------|--------|
| Front | Left | 225 / 60 / 18 / 100 / V / Aluminium | 5,8 mm | Bridgestone | Summer |
| | Right | 225 / 60 / 18 / 100 / V / Aluminium | 5,3 mm | Bridgestone | Summer |
| Rear | Left | 225 / 60 / 18 / 100 / V / Aluminium | 5,5 mm | Bridgestone | Summer |
| | Right | 225 / 60 / 18 / 100 / V / Aluminium | 5,4 mm | Bridgestone | Summer |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (normal) | 1 |
| Number of charging cables (rapid charge) | 1 |

Interior, Dirty, Cleaning



Roof liner, Dirty, Cleaning



Wing FL, Chemical polution, Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)




Wing RR, Dent(s), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Side window trim RR, Dent(s), Replace and paint



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Polish



| | |
|-----------------------|--|
| Kenteken | N605LN |
| Merk Model | Ford Sneller rijden via Mossel Mustang Mach-E 198kW/ 75,7kWh RWD |
| Brandstofsoort | Elektrisch |
| Datum deel1 | 18-11-21 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|-----------------|----------------|-----------------------------------|
| 14-10-25 | 83.610 | APK |
| 14-10-25 | 83.610 | Onderhoudsbeurt |
| 14-10-25 | 83.610 | Remvloeistof |
| 14-10-25 | 83.610 | Ruitenwischerblad(en) achterzijde |
| 14-10-25 | 83.610 | Ruitenwischerblad(en) voorzijde |
| 30-04-24 | 53.094 | Reparatie band(en) |
| 16-10-23 | 40.730 | Onderhoudsbeurt |