



Ford Transit Connect: VRG10X

Vinnumber:	WF0SXXWPGSNT33184	Versionname:	Transit Connect 1.5 TDCI 74kW Trend L2 GB automaat
First Registrationdate:	30/06/2022	Fiscalpower:	
Expertise Mileage:	172561	Power Kw:	74
Bodytype:		Body colour	Standaardlak: Frozen White
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Diesel	Parking lot	436
Number of seats	2		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	1	Rear parking sensors
GPS		Sliding door right-side
Manual climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 16 / 96 / H / Steel	4,2 mm	Vredestein	All season
	Right	205 / 60 / 16 / 96 / H / Steel	4,2 mm	Vredestein	All season
Rear	Left	205 / 60 / 16 / 96 / H / Steel	6,3 mm	Vredestein	All season
	Right	205 / 60 / 16 / 96 / H / Steel	4,1 mm	Vredestein	All season

Assistance equipment

Ignition key, Missing, Replace

No pictures to display

Interior, Stain, Cleaning



Outside rear-view mirror housing L, Scratch(es), Replace



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)





Bumper F, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace



Wing FR, Scratch(es), Repair and paint (complete)



Bumper R, Broken, Replace





Boot door panel RR, Dent(s), Repair and paint (complete)



Boot door panel RL, Dent(s), Repair and paint (complete)



Rear light L, Broken, Replace



Bumper corner RR, Dent(s) and scratch(es), Replace and paint



Roof, Dent(s) and scratch(es), Repair and paint (complete)



Kenteken	VRG10X
Merk Model	Ford Transit Connect 1.5 TDCI 74kW Trend L2 GB automaat
Brandstofsoort	Diesel
Datum deel1	30-06-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
17-03-26	172.329	Turboslang
29-12-25	165.077	Distributieriem met spanrol
29-12-25	165.077	Onderhoudsbeurt
29-12-25	165.077	Reparatie band(en)
29-12-25	165.077	Riem/ multiriem
29-12-25	165.077	Waterpomp
13-10-25	156.281	Remschijf + blokken voor
07-07-25	144.195	APK
07-07-25	144.195	Fijnstofmeting
07-07-25	144.195	Onderhoudsbeurt
07-07-25	144.195	Remvloeistof
13-01-25	122.048	Onderhoudsbeurt
13-01-25	122.048	Remschijf + blokken achter
13-01-25	122.048	Ruitenwisserblad(en) voorzijde
30-12-24	116.745	Vervanging band
19-08-24	105.345	Onderhoudsbeurt
19-08-24	105.345	Uitlijnen voorwielen
08-04-24	87.609	Onderhoudsbeurt
08-04-24	87.609	Remblokken voorzijde
09-11-23	68.540	Onderhoudsbeurt
09-11-23	68.540	Remblokken achterzijde
09-11-23	68.540	Remvloeistof
07-06-23	46.719	Onderhoudsbeurt
07-06-23	46.719	Remschijf + blokken voor
27-12-22	25.559	Onderhoudsbeurt