



Renault Master: VHX80B

Vinnumber:	VF1VB000466287878	Versionname:	Master T35 2.3DCI EUVI Energy 121kW FWD CC L3H1
First Registrationdate:	31/12/2020	Fiscalpower:	
Expertise Mileage:	234144	Power Kw:	121
Bodytype:		Body colour	Blanc Mineral
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Diesel	Parking lot	1190
Number of seats	3		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	1	Rear view camera
GPS		
Manual climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 65 / 16 / 112 / T / Steel	5,5 mm	Bridgestone	All season
	Right	225 / 65 / 16 / 112 / T / Steel	5,1 mm	Bridgestone	All season
Rear	Left	225 / 65 / 16 / 112 / T / Steel	5,4 mm	Goodyear	All season
	Right	225 / 65 / 16 / 112 / T / Steel	3,7 mm	Goodyear	All season

Assistance equipment

Rear-view camera, Not functioning (well), Replace



Glove compartment lid, Broken, Replace



Ignition key, Missing, Replace

No pictures to display

Interior, Stain, Cleaning



Shutter / cover, Missing, Replace



Shutter / cover, Broken, Replace



Side wall RL, Crack, Repair and paint (complete)



Wing FL, Dent(s), Paintless dent repair



Mirror side repeater L, Broken, Replace



Outside rear-view mirror housing L, Scratch(es), Replace



Windscreen, Crack, Replace



Bumper F, Scratch(es), Smart repair



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)





Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Mirror side repeater R, Scratch(es), Replace



Outside rear-view mirror housing R, Scratch(es), Replace



Door trim FR, Scratch(es), Replace



Rear light R, Broken, Replace



Bodywork, Chemical polution, Polish



Wheel cover RR, Missing, Replace



Kenteken	VHX80B
Merk Model	Renault Master T35 2.3DCI EUVI Energy 121kW FWD CC L3H1
Brandstofsoort	Diesel
Datum deel1	31-12-20

Datum reparatie	Kilometerstand	Reparatie omschrijving
18-03-26	226.120	Remschijf + blokken achter
18-03-26	226.120	Remschijf + blokken voor
13-01-26	221.622	Hoofdkoppeling cilinder
09-01-26	0	Koppeling compleet
18-11-25	217.955	APK
18-11-25	217.955	Fijnstofmeting
30-05-25	210.529	Remvloeistof
30-05-25	210.529	Uitlijnen voorwielen
30-05-25	210.529	Vervanging band
30-05-25	210.529	Vlieg wiel
02-12-24	197.355	Accu
02-12-24	197.355	APK
02-12-24	197.355	Fijnstofmeting
02-12-24	197.355	Onderhoudsbeurt
02-12-24	197.355	Remblokken achterzijde
02-12-24	197.355	Remklauw(en) achterzijde
21-08-24	187.942	Remblokken voorzijde
21-08-24	187.942	Remschijf + blokken achter
21-08-24	187.942	Ruitenwischerblad(en) voorzijde
21-08-24	187.942	Vervanging band
18-12-23	166.266	APK
18-12-23	166.266	Brandstoffilter
18-12-23	166.266	Fijnstofmeting
18-12-23	166.266	Multiriem inclusief spanner
18-12-23	166.266	Onderhoudsbeurt
18-12-23	166.266	Remslijtage indicator
18-12-23	166.266	Sleutelbatterij
20-09-23	154.676	Remblokken achterzijde
20-09-23	154.676	Remschijf + blokken voor
10-08-23	149.025	Vervanging band
15-05-23	132.903	Luchtfilter
15-05-23	132.903	Onderhoudsbeurt
15-05-23	132.903	Remvloeistof
15-05-23	132.903	Ruitenwischerblad(en) voorzijde
02-03-23	116.860	Remblokken voorzijde
02-03-23	116.860	Remschijf + blokken achter
31-08-22	86.132	Brandstoffilter
31-08-22	86.132	Onderhoudsbeurt
31-08-22	86.132	Vervanging band
15-10-21	42.238	Onderhoudsbeurt

Datum reparatie	Kilometerstand	Reparatie omschrijving
15-10-21	42.238	Remblokken achterzijde
15-10-21	42.238	Remblokken voorzijde
29-09-21	39.890	Ruitenwisserblad(en) voorzijde