

Vehicle details

VIN	SJNFAAZE1 U0110463	Brand	NISSAN	Maintenance date	-
Licence Plate		Model	Leaf N-CONNECTA 40kWh 5d APL	Maintenance mileage	-
Registration date	17/07/2021	Year	2021	Exterior Color	White Solid
Odometer	140 801 km	Engine size	-	Interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	20/07/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

1



Part

Alloy wheel 17"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

4



Part

Bumper

Position

Back

Damages

Broken

Severity

-

Repair mode

Replace

5



Part

Bumper moulding

Position

Back

Damages

Broken

Severity

-

Repair mode

Replace

6



Part

Spoiler

Position

Back

Damages

Scratched

Severity

-

Repair mode

Repair

8



Part

Rocker panel cap

Position

Back right

Damages

Missing

Severity

-

Repair mode

Replace

9



Part

Wing

Position

Back right

Damages

Dent & Chips

Severity

-

Repair mode

Repair

10



Part

Door

Position

Back right

Damages

Dent & Chips


Severity

-

Repair mode

Repair

11



Part

Wing

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Repair

12



Part

Bumper

Position

Front

Damages

Scratched


Severity

-

Repair mode

Repair

13



Part

Step plate

Position

Back right

Damages

Dented

Severity

-

Repair mode

For info

Interior damage

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

7



Part	Interior tailgate lining
Position	-
Damages	Broken
Severity	-
Repair mode	Replace