MACADAM









## DS 7: HC-869-PQ

| | | | |
|---|---|---|---|
| Vinnumber: | **VR1J4DGZ7SY528134** | Versionname: | **DS DS 7 PLUG-IN 225 ETOILE VP [5P] bva 8-225CH-10cv (SUV)** |
| First Registrationdate: | **25/03/2025** | Fiscalpower: | |
| Expertise Mileage: | **20794** | Power Kw: | **165** |
| Bodytype: | **SUV** | Body colour | **Grey** |
| Gearbox: | **Automatic** | Paint type | **Metalic** |
| Transmission: | **Front** | Interior colour | **Black** |
| Fueltype: | **Plug-in hybrid** | Type of rims (mounted) | **Aluminium** |
| Engine functioning | **Yes** | Dashboard color | **Black** |
| Battery functioning | **Yes** | | |
| Vehicle running | **Yes** | | |
| Number of doors | **5** | | |
| Number of seats | **5** | | |
| Number head rests | **5** | | |
| Type of rims (mounted) | **Aluminium** | | |
| Category | **Passenger Car** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **2** | Radio | |
| Number keys remote | **2** | Seats electric F L | |
| GPS big screen color | | Seats electric F R | |
| Windows electric F | | Sun Roof electric | |
| Windows electric R | | Panoramic roof | |
| Cruise Control | | Central consol F | |
| Steering wheel multifunctional | | Luggage cover | |
| Steering wheel leather | | Headlights Xenon/LED/Laser | |
| Type of climate control | **Autom climate control** | Front parking sensors | |
| | | Rear parking sensors | |
| | | Rear view camera | |
| | | Seat cover lining | **Lining Leather** |

## Tyres

| | | | | |
|---|---|---|---|---|
| Summer tyres: | **235/50/19/103 V** | | | |
| | Fr.L. | **Michelin: 45%** | Fr.R. | **Michelin: 45%** |
| | Re.L. | **Continental: 30%** | Re.R. | **Continental: 45%** |

| | |
|---|---|
| Tyre profile depth FL | **5.2** |
| Tyre profile depth FR | **5.2** |
| Tyre profile depth RL | **6.1** |
| Tyre profile depth RR | **5.2** |
| Tyre size FL | **235/50 R 19 103 V** |
| Tyre size FR | **235/50 R 19 103 V** |
| Tyre size RL | **235/50 R 19 103 V** |
| Tyre size RR | **235/50 R 19 103 V** |
| Tyre type FL | **Summer** |
| Tyre type FR | **Summer** |
| Tyre type RL | **Summer** |
| Tyre type RR | **Summer** |
| Tyre make FL | **261** |
| Tyre make FR | **261** |
| Tyre make RL | **256** |
| Tyre make RR | **256** |

## Assistance equipment

**Roof liner, Unclasped, Dismount/Mount**





Steering column top cover, Missing, Replace




Interior trim, Incomplete, Replace




Wing trim FL, Scratch(es), Replace






Outside rear-view mirror base L, Missing, Replace




Door window FL, Missing, Replace



Door RL, Scratch(es), Paint





Wing RL, Dent(s) and scratch(es), Repair and paint (complete)





Wing trim RL, Scratch(es), Replace





Bumper F, Broken, Repair and paint (complete)







Bumper moulding F, Scratch(es), Replace






Number plate F, Missing, Repair/replace (lump sum)




Door window FR, Broken, Replace




Wing trim FR, Scratch(es), Replace






Charging cable (normal), Missing, Replace




Number plate R, Missing, Repair/replace (lump sum)




ALPHABET

# Historique Maintenance

Immatriculation: **HC-869-PQ** Date de 1ère immatriculation: **25/03/2025**

Modèle: **DS 7 PLUG-IN 225 ETOILE VP [5P] bva 8-225CH-10cv (SUV)**

| Date | Kilométrage | Fournisseur | Descriptif |
|---|---|---|---|
| 14/08/2025 | 7.290 | FLEET SOLUTIONS FRANCE | REMPLACEMENT PNEUS ETE |