



VSSZZZKLZNR032348

Angaben zum Fahrzeug

Halter		Besichtigungszustand	bedingt: Licht/Nässe/Schmutz
Kennzeichen		Laufleistung (abgelesen)	22.176 km
Hersteller	Seat	Restlauf bis Service	608 Tag(e)
Typ/Modell	LEON SP	HU (Abgelesen aus ZBI)	02/2028
Fahrgestellnummer	VSSZZZKLZNR032348	Leistung / Hubraum	110 kW / 1.498 ccm
Erstzulassung	14.01.2022	Polster/Farbe	Stoff / Schwarz
Letzte Wartung	02/2026, 17.885 km	Lackierung	Schwarz
Kraftstoffart	Hybr.Benzin/E	Getriebe	Automatik

Zustandsbericht

Wertmindernde Faktoren

Nr.	Bauteilgruppe	Beschreibung
1	Tür hinten links	Tür - verkratzt / verschürft - Smart Repair

Gebrauchsspuren

Nr.	Bauteilgruppe	Beschreibung
Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.		

Fehlteile

Fehlteil
Unterlagen - HU Bescheinigung

Festgestellte Nachlackierungen

Nr.	Ort
Keine feststellbar	

Hauptbereifung

Achse	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Verktgl.	Zul.
1	225/45 R17 91W	Nexen	Sommerreifen	5mm - 6mm	i.O.	i.O.
2	225/45 R17 91W	Nexen	Sommerreifen	5mm - 6mm	i.O.	i.O.

Ersatz

Typ	Reifengröße	Hersteller	Reifentyp	Profiltiefe	Ablaufdatum
Notrad	125/70 R18 99M	Sonstige	Sommerreifen	4	

Der Verschleißzustand sowie evtl. Schäden an der Bereifung sind wertmäßig berücksichtigt.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Auto Partner: DTS
GmbH
Deizisauer Str. 24
73770 Denkendorf

Besichtigungsdatum: 29.06.2026
Protokollnummer: 46267956
Erstellt durch: Markus Böttcher
Besichtigt durch: Weber



Angaben zum Fahrzeug

Hersteller	Seat	Besichtigungszustand	bedingt: Licht/Nässe/Schmutz
Typ/Modell	LEON SP	Laufleistung (abgelesen)	22.176 km
Fahrgestellnummer	VSSZZZKLZNR032348	Erstzulassung	14.01.2022

Angaben zum Auftrag:

Auftragsgemäß erfolgte die Fahrzeugzustandsbewertung in demontagefreien Zustand.

Grundlage dieses Produktes stellt der Leitfaden für Fahrzeugrücknahmen und Bewertungen gemäß des Schadengrenzmusterkatalog des Auftraggebers dar. Die expliziten Feststellungen im Einzelfall trifft der Sachverständige objektiv im Rahmen der vorgegebenen Standards aufgrund eigener Sachkunde.

Fahrzeug-Identifizierung:

Die Fahrzeug-Identifizierungsnummer (FIN) wurde am Fahrzeug abgelesen und die Übereinstimmung im Verlauf der Besichtigung durch den Unterzeichner mit den vorgelegten Unterlagen festgestellt.

Besichtigungsbedingungen:

Eine ordnungsgemäße Sichtprüfung der Lackierung und der Karosserie war wegen unzureichender Lichtverhältnisse/ Nässe oder Verschmutzung nur eingeschränkt möglich.

Allgemeinzustand:

Das Fahrzeug weist dem Alter und Einsatzzweck entsprechende Gebrauchsspuren auf.

Unterschrift Sachverständiger (Markus Böttcher)

Vorliegendes Druckexemplar wurde auf elektronischem Wege erzeugt. Der benannte Sachverständige versichert, dass der Inhalt die von ihm getroffenen Feststellungen korrekt wiedergibt. Es ist ohne Originalunterschrift gültig.

Übersichtsfotos



Abbildung 1: FIN



Abbildung 2: Schräg vorne



Abbildung 3: Schräg vorne



Abbildung 4: Schräg hinten



Abbildung 5: Schräg hinten



Abbildung 6: Montierte Bereifung

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Besichtigungsort
TÜV SÜD Auto Partner: DTS
GmbH
Deizisauer Str. 24
73770 Denkendorf

Besichtigungsdatum: 29.06.2026
Protokollnummer: 46267956
Erstellt durch: Markus Böttcher
Besichtigt durch: Weber




Abbildung 7: Innenraum vorne



Abbildung 8: Laderaum




Abbildung 9: Kombiinstrument




Abbildung 10: Instrumententafel




Abbildung 11: Dokumente



Abbildung 12: Dokumente



Beschädigungsfotos



Beschädigung #1: Tür hinten links: Tür - verkratzt / verschürft - Smart Repair



Beschädigung #1: Tür hinten links: Tür - verkratzt / verschürft... Smart Repair



Beschädigung #1: Tür hinten links: Tür - verkratzt / verschürft - Smart Repair

EC Certificate of Conformity

046CC0118698



www.PS-Team.de

Complete vehicles

The undersigned hereby certify that the vehicle:

- 0.1.

Make (Trade name of manufacturer):

SEAT
- 0.2.

Type:

KL
- 0.3.

Variant:

SDFYAX0
- 0.4.

Version:

FD7MFD7CW00248IVL1BAA15A8H
- 0.5.

Commercial name:

SEAT LEON SP
- 0.6.

Interpolation family's identifier:

IP-MQB87WZ_A1_0575-VSS-1
- 0.7.

ATCT family's identifier:

AT-5Q0_0V_0280_000-VSS-1
- 0.8.

PEMS family's identifier:

09-VSS-715W_KL_DFYA_FD7_A_1-000
- 0.9.

Roadload family's identifier:

RL-DQ200_7F_20_001-WVVW-1
- 0.10.

Roadload matrix family's identifier (if applicable):
- 0.11.

Periodic regeneration family's identifier:

PR-VW_00221_00_000-WVVW-1
- 0.12.

Evaporative test family's identifier:

EV-AU_DGW_D_AZAAAA-WVVW-1
- 0.13.

Vehicle category:

M1
- 0.14.

Company name and address of manufacturer:

SEAT, S.A.
Autovia A-2, Km. 585
ES-08760 Martorell

- 0.15.

Location and method of attachment of the statutory plates:

On the right A-pillar, glued or bonded
- 0.16.

Location of the vehicle identification number:

In the engine compartment, right
- 0.17.

Vehicle identification number:

VSSZZZKLZNR032348
- 0.18.

Date of manufacture of the vehicle:

2021-11-22

conforms in all respects to the type described in approval e9*2007/46*3167*14 issued on 2021-07-28 and can be permanently registered in Member States having right hand traffic and using metric units for the speedometer and metric units for the odometer.

Martorell, 2021-11-22

Martorell, 2021-11-22

NO 16.2.: with trailer axle 2+5 kg##NO
35.: alt. to pos 35 with deviating val. in pos 49:##205/55 R16 91V#7.0JX16 ET43;
##205/55 R16 94V XL#7.0JX16 ET43;##205/55 R16 91V#6.5JX16 ET46;##205/55 R16 94V
XL#6.5JX16 ET46;##225/40 R18 92V XL#7.5JX18 ET46;##225/45 R17 91W#7.5JX17 ET46;#
#205/50 R17 93H M+S#7.5JX17 ET46;##205/55 R16 91H M+S#7.0JX16 ET43;##205/55 R16
91H M+S#6.5JX16 ET46;##225/40 R18 92V XL M+S#7.5JX18 ET46;##

Joaquin Serra Oliveras
Director Quality Assurance

Adria Martin Milià
Head of Technical Conformity

Internal Manufacturer Data

VSSZZZKLZNR032348



49. CO₂ emissions/fuel consumption/electric energy consumption:

1. All power trains except pure electric vehicles (if applicable):

NEDC values	CO ₂ emissions		Fuel consumption [l/100 km]			
	Petrol/Diesel g/km	LPG / CNG g/km	Others g/km	Petrol/Diesel [L]	LPG / CNG [L]/[m ³]	Others [L]
Urban conditions	140	---	---	6.1	---	---
Extra-urban conditions	97	---	---	4.2	---	---
Combined	113	---	---	4.9	---	---
Weighted, combined	---	---	---	---	---	---

Deviation factor (if applicable):

Verification factor (if applicable):

2. Pure electric vehicles and OVC hybrid electric vehicles (if applicable)

Electric energy consumption (weighted, combined): [Wh/km]

Electric range: [km]

3. Vehicle fitted with eco-innovation(s):

3.1. General code of the eco-innovation(s):

3.2. Total CO₂ emissions savings due to the eco-innovation(s):

3.2.1. NEDC savings (if applicable)

3.2.2. WLTP savings (if applicable)

Diesel / Petrol

LPG / NG [g/km]

Others [g/km]

4. All power trains, except pure electric vehicles (if applicable)

WLTP values	CO ₂ emissions		Fuel consumption: [l/100 km]			
	Petrol/Diesel g/km	LPG / CNG g/km	Others g/km	Petrol/Diesel [L]	LPG / CNG [L]/[m ³]	Others [L]
Low	171	---	---	7.6	---	---
Medium	126	---	---	5.6	---	---
High	114	---	---	5.0	---	---
Extra High	136	---	---	6.0	---	---
Combined	132	---	---	5.8	---	---
Weighted, combined	---	---	---	---	---	---

5.1. Pure electric vehicles (if applicable)

Electric energy consumption

[Wh/km]:

Electric range [km]:

Electric range city [km]:

Electric range city (EAER) [km]:

For special purpose vehicles:

Designation in accordance with Annex II, Section 5:

52. Remarks:

NO 16.2.: with trailer axle 2+5 kg##NO
35.: alt. to pos 35 with deviating val. in pos 49:##205/55 R16 91V#7.0JX16 ET43;
##205/55 R16 94V XL#7.0JX16 ET43;##205/55 R16 91V#6.5JX16 ET46;##205/55 R16 94V
XL#6.5JX16 ET46;##225/40 R18 92V XL#7.5JX18 ET46;##225/45 R17 91W#7.5JX17 ET46;#
#205/50 R17 93H M+S#7.5JX17 ET46;##205/55 R16 91H M+S#7.0JX16 ET43;##205/55 R16
91H M+S#6.5JX16 ET46;##225/40 R18 92V XL M+S#7.5JX18 ET46;##

1.	Number of axles / wheels:	2 / 4
3.	Powered axles (number, position): Interconnection of powered axles:	1 Axle 1 -----
3.1.	Specify if the vehicle is non-automated/automated/fully automated:	non-automated
4.	Wheelbase[mm]:	2672
4.1.	Axle spacing [mm]:	2672
5.	Length [mm]:	4642
6.	Width [mm]:	1799
7.	Height [mm]:	1450
13.	Mass in running order [kg]:	1441
13.2.	Actual mass of the vehicle [kg]:	1486
16.	Technically permissible maximum masses:	
16.1.	Technically permissible maximum laden mass [kg]:	1990
16.2.	Technically permissible mass on each axle (1./2.) [kg]:	1000 / 1040
16.4.	Technically permissible maximum mass of the combination [kg]:	3490
18.	Technically permissible maximum towable mass in case of:	
18.1.	Drawbar trailer [kg]:	-----
18.3.	Centre-axle trailer [kg]:	1500
18.4.	Unbraked trailer [kg]:	720
19.	Technically permissible maximum static vertical mass at the coupling point [kg]:	80
20.	Manufacturer of the engine:	Volkswagen AG
21.	Engine code as marked on the engine:	DFV
22.	Working principle:	Positive ignition / 4 stroke
23.	Pure electric:	no
23.1.	Class of Hybrid (electric) vehicle:	NOVC-HEV
24.	Number and arrangement of cylinders:	4; in Line
25.	Engine capacity [cm³]:	1498
26.	Fuel:	petrol/hybrid
26.1.	Mono fuel/Bi fuel/Flex fuel/Dual fuel:	mono fuel vehicle
26.2.	Type of dual fuel engine:	-----
27.	Maximum power	
27.1.	Maximum net power [kW at min ⁻¹] (internal combustion engine):	110.00 / 5000
27.2.	Maximum hourly output [kW] (electric motor):	-----
27.3.	Maximum net power [kW] (electric motor):	9.40
27.4.	Maximum 30 minutes power [kW] (electric motor):	-----

28.	Gearbox (type):	automatic
28.1.	Gear	-----
28.1.	Gearbox ratios:	-----
28.1.2.	Final drive ratio:	-----
28.1.2.	Total gear ratios:	-----

Maximum speed [km/h]: 218

Axle(s) track (1./2.) [mm]: 1544 / 1514

Fitted tyre/wheel combination/energy/efficiency class of RRC/type category used for CO₂ determination:

Axle 1: 225/45 R17 91W / 7.5JX17 ET46 / B / C1

Axle 2: 225/45 R17 91W / 7.5JX17 ET46 / B / C1

Trailer brake connections: -----

Code for bodywork: AC

Colour of vehicle: BLACK

Number and configuration of doors: 5 / le. 2, ri. 2, ba. 1

Number of seating positions (including the driver): 5

Seat(s) designated for use only when the vehicle is stationary: ---

Number of wheelchair user accessible position: ---

Sound level

Stationary [dB(A) at min⁻¹): 75.60 / 3750

Drive-by [dB(A)]: 67.00

Exhaust emission level: EURO 6 AP

Parameters for emission testing of Vind: 1566

Test mass [kg]: -----

Frontal area [m²]: -----

Road load coefficients

47.1.3.0.10 [N]	47.1.3.1.11 [N/(km/h)]	47.1.3.2.12 [N/(km/h)²]
120.505736	0.173000	0.030734

Driving cycle: 3b

Driving cycle class: -----

Downscaling factor (f_{dec}): -----

Capped speed: no

Exhaust emissions: 715/2007/2018/1832AP

1.2. Test procedure: Type 1 (NEDC average values, WLTP highest values) [mg/km] or WHSC (EURO VI)

Petrol /	CO	THC	NMHC	NO _x	THC + NO _x	NH ₃	Particles	Particles #
Diesel	134.8	21.2	18.1	18.5	-----	-----	0.0000	0.08E11
LPG/CNG	-----	-----	-----	-----	-----	-----	-----	---
Other	-----	-----	-----	-----	-----	-----	-----	---

2.2. Test procedure: WHTC (EURO VI) [mg/kWh]

Petrol /	CO	THC	NMHC	CH ₄	NO _x	NH ₃	Particles	Particles #
Diesel	-----	-----	-----	-----	-----	-----	-----	---
LPG/CNG	-----	-----	-----	-----	-----	-----	-----	---
Other	-----	-----	-----	-----	-----	-----	-----	---

Smoke corrected absorption coefficient [m⁻¹): -----

Declared maximum RDE values (if NO_x [mg/km] Particles (number) with exponent (#/km)

Complete RDE trip: 60.0 6.00 E11

Urban RDE trip: 60.0 6.00 E11

MOBILITY CONCEPT

LVV Nr	4895626
Hersteller	Seat
Model	León
Variante	FR 1.5 eTSI MHEV
Listenpreis	29.592,46
VIN	VSSZZZKLZNR032348
Erstzulassungsdatum	14.1.2022
Kennzeichen	M-GZ 1076

Schadensfälle der int. Belegnummer: 4895626

29.07.2026

Schadennummer	Unfalldatum	Beschädigung	Schadenhöhe in EUR
2026108996	07.06.2026	Fahrerseite Tür hinten	

- Seite 1 von 1 -