

» Overview

Order number: 1002406808
Order completed: 14.04.2026 16:12
Report number: 10424579
VIN: WAUZZZFY3N2042671



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SUV
Make:	Audi
Model:	Q5
Manufacturers and type code:	0588 / BYQ
Date of first registration:	05.04.2022
Mileage:	62,737 km
Proof of mileage:	ReadOff
Exterior colour:	Mythossschwarz Metallic
Roof colour:	Mythossschwarz Metallic
Propulsion:	4 Wheel-drive
Fuel:	Diesel
Engine size (cc):	3,000 ccm
Performance:	210 kW (286 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	6
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 8-speed
Upholstery type:	Lining leather
Interior colour:	schwarz-schwarz/schwarz-schwarz/schwarz/titangrau
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	06.2027
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	7,200 KM

3-zone deluxe automatic air conditioning	Country group A
48-V electric system	Data module, Europe
4-way lumbar support for the front seats	Daytime running lights
6-cyl. turbo diesel engine 3.0 l/210 kW V6 TDI common rail base engine is T7V/T2P	Deselection of Audi phone box
6-cylinder diesel engine 3.0 l unit 059.P	Diesel engine
Accent surfaces, Matt Black	Digital radio reception
AdBlue tank with increased capacity	Direct control code
Adhesive film	Disc brakes in front, 17-inch (ECE)
Ambient Lighting package	Disc brakes in rear, 17-inch (ECE)
Assist package City	Door sill trims with aluminum inlays, front, illuminated, S logo
Assist package Tour	Driver and front passenger airbag with front passenger airbag deactivation
Audi active lane assist	Driving on the right
Audi adaptive cruise control	Electric auxiliary air heater
Audi AG	Electromechanical parking brake
Audi connect emergency call & service with Audi connect remote & control	Electromechanical power steering
Audi connect navigation & infotainment	Electronic immobilizer
Audi drive select	Emission standard EU6 AP
Audi pre sense city	Equipment options subset for Germany
Audi pre sense rear	Extended pedestrian protection
Audi smartphone interface	Exterior mirror housings in body color
Audi sound system	Exterior mirrors, power-adjustable, heated and power-folding, auto-dimming on both sides, with memory feature
Audi virtual cockpit plus	Filler neck module 1 without insert
Axial and vertical adjustable steering column	First-aid kit with warning triangle and high-visibility vests
Basic	Floor mats in front and rear
Basic equipment variant	Front head restraints
Battery 380 A (68 Ah)	Front seats, electrically adjustable with memory function for driver seat and exterior mirrors
Belt-driven integrated starter alternator 48 V 110 - 250 A	Front seats, electrically adjustable with memory function for the driver seat
Beverage holders	Fuel system for diesel engine
Black roof rails with roof rack detection system	Fuel tank with increased capacity
Black Styling package	Gearshift/selector lever handle
Bluetooth interface	Headliner in Black fabric
Business package	Head-up Display
Camera-based traffic sign recognition	High-beam control
Carrier frequency 433.92 MHz-434.42 Mhz	Increase in initial standard fuel filling
Category 0	Inlays, Micrometallic, Silver
Child Safety package	Installation parts for six-cylinder engine
Child-proof lock, electrically operated	Instrument cluster, km/h speedometer
Comfort center armrest, front	Interior mirror, automatically dimming, frameless
Control code	ISOFIX child seat mounting and top tether for the outer rear seats
Control of series production	ISOFIX child seat mounting for the front passenger seat
Convenience key, without Safelock	



Assessment

- Vehicle Inspection Report -

Number: 10424579
From: 15.04.2026

Labels in English and German	Seat belt reminder
Leather steering wheel, 3-spoke with multifunction plus	Seat heating, front
Leather/mono.pur 550 artificial leather combination	Service indicator 30 000 km or 1 year (variable)
LED headlights	Side airbags, front and rear and head airbag system
LED rear lights	Side assist
Left exterior mirror, aspherical	Special identification label (EU)
Left-hand drive	Sport suspension
Loading floor	Sportsback
Loading sill protector, stainless steel	Standard
Luggage compartment cover	Standard climatic zones
Luggage compartment lid, electrically opening and closing	Standard manufacturing sequence
Luggage compartment mat	Standard pedal cluster
Manual in German	Standard seats in front
Mild hybrid	Standard suspension
MMI navigation plus with MMI touch	Standard wheel bolts
Model name as per new output designation	Standard-production quality
No self-collection	Start-stop system
No special edition	Storage and Luggage Compartment package
No special purpose vehicle, standard equipment	Sun visor on driver and front passenger side
Non-smoker's package	Sunshade, manual for the door windows, rear
Not hot country	tiptronic
Not leather-covered	tiptronic
Operating permit, alteration	Tire pressure loss indicator
Parking system plus	Tire repair kit
Part set without country-specific prescriptive standard	Tires 235/55 R19 101W
Partition net	Tires without specification of tire brand
Passenger car design	Transit coating (type 2)
Preparation for functions on demand	Two-tone horn
Preparation for trailer hitch	Type approval country Germany
Privacy glass (dark-tinted windows)	Vehicle class differentiation -FY0/FYF-
Production wheels	Vehicle tool kit (without vehicle jack)
quattro	Vehicles with special upgrade measures
quattro with self-locking center differential	Weight category front axle weight range 8
Rear and side windows with heat-insulating glazing	Weight range 8 installation control only, no requirement forecast
Rear seat bench plus	Wheels, 10-spoke, 7.0J x 17, 235/65 R17 winter tires
Rear trim panel (ECE)	Wheels, 5-spoke V, Graphite Gray, gloss turned finish, 8.0J x 19, 235/55 R19 tires
Refrigerant R1234yf	Windshield with heat-insulating/ acoustic glazing
Regional code " ECE " for radio	With multifunction camera
Reinforced bumpers	With special labels safety certificates for Germany
Reversing camera	Without acoustic vehicle alerting system
Right exterior mirror, aspherical	Without additional front underbody guard
Roof spoiler	Without additional warning lights
S line	

Without antenna amplifier
Without auxiliary heater/parking heater
Without Car2X
Without charging cable for public charging (AC), mode 3
Without danger alarm system
Without decorative films/emoles
Without electric motor (hybrid)
Without fire extinguisher
Without front license plate carrier
Without garage door opener
Without headlamp washer system
Without ignition/starter switch locking system, without steering lock
Without integrated toll system
Without locking and starting systems
Without mains cable for domestic connector for the e-tron charging system
Without mains cable for industrial connector for the e-tron charging system
Without preconditioning
Without preparation for VTS (vehicle tracking system)
Without roof insert (standard roof)
Without seat ventilation/massage seat
Without special body measures
Without step
Without vehicle inlet
Without wall mount

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental	Front	Left	Summer	Aluminium	235/55 R 19 101 W	6.0 mm
Continental	Front	Right	Summer	Aluminium	235/55 R 19 101 W	6.0 mm
Continental	Rear	Left	Summer	Aluminium	235/55 R 19 101 W	6.0 mm
Continental	Rear	Right	Summer	Aluminium	235/55 R 19 101 W	6.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 09.2026

Compressor present: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Tailgate / Boot	Scratch(es)	Paint
2	Preparationtime metal painting	Paint preparation	Execute
3	Door FL	Scratch(es)	Polish
4	Door RL	Scratch(es)	Polish

» Usage Damages

Nr	Location	Damage type	Repair type
1	Bumper F	Scratch(es)	Acceptable

» Commercial devaluation

Known previous damages:	No
Previous damages detectable:	No
Repainting present:	No
Paint thickness measurement performed:	Yes - with abnormalities/deviations

PAINTTHICKNESS MEASUREMENT RESULTS

Part	Paint (µm)
Paint thickness Wing FL (µm)	196.0
Paint thickness Door FL (µm)	204.0
Paint thickness Door RL (µm)	205.0
Paint thickness Wing RL (µm)	193.0
Paint thickness Trunk (µm)	134.0
Paint thickness Wing RR (µm)	197.0
Paint thickness Door FR (µm)	192.0
Paint thickness Door RR (µm)	211.0
Paint thickness Wing FR (µm)	191.0
Paint thickness Bonnet (µm)	203.0
Paint thickness Roof (µm)	205.0
At least 3 measurements were carried out per component.	

» Notes On The Assessment**Details of the assignment and the scope of the assessment:**

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WAUZZZFY3N2042671

VIN checked and matches documentation

Vehicle condition:

Cleaned

Inspection condition:

Wet

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

No

Engine test carried out:

Yes

» Remarks

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4



Rear Right 3/4




Mileage



Tools



Sill outer L



Sill outer R



Chassis nr



Wheel FL



Wheel FR




Wheel RL




Wheel RR



Central console




Engine compartment



Documents



Interior arrangement



Registration Certificate



Paint thickness Trunk



Paint thickness Roof



Paint thickness Door RL



Paint thickness Door RR



Paint thickness Door FL



Paint thickness Door FR



Paint thickness Bonnet



Paint thickness Wing RL



Paint thickness Wing RR




Paint thickness Wing FL




Paint thickness Wing FR



History Maintenance




Interior - front




Interior - rear



Tirefit expiration date



Underbody scan



GPS/Radio

» Devaluation Damages


DEVALUATION FACTORS

1 - Tailgate / Boot - Scratch(es) - Paint




2 - Preparationtime metal painting - Paint preparation - Execute

3 - Door FL - Scratch(es) - Polish



4 - Door RL - Scratch(es) - Polish



USAGE DAMAGES

1 - Bumper F - Scratch(es) - Acceptable

