


Vehicle details

VIN	LRW3E7FA8 LC097892	Brand	TESLA	Maintenance date	-
		Model	Model 3 Standard Range Plus RWD 4d ActieAuto	Maintenance mileage	-
Registration date	09/12/2020	Year	2020	Exterior Color	White Solid
Odometer	163 617 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	27/07/2026
-----------------	------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element


Vehicle charger	✓
Wireless charger	✓

Technical Document

Spare key	✓
Card Key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 235/45/18 Summer 5.5 mm



Michelin 235/45/18 Summer 5.0 mm



Michelin 235/45/18 Summer 6.0 mm

Michelin 235/45/18 Summer 5.5 mm

Exterior

2



Part	Windscreen
Position	-
Damages	Broken
Severity	-
Repair mode	Replace

3



Part	Panoramic Roof
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace

5



Part	Alloy wheel 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

6



Part	Bumper
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

7




Part	Alloy wheel 18"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

8



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

9



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

10



Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

11



Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

Interior damage

1



Part	Boot carpet
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Fabric door lining
Position	Back left
Damages	Not conform
Severity	-
Repair mode	Replace