



CITROËN C4: 0623-MBF

Vinnnumber:	VR7BBYHSANE054820	Versionname:	Citroen BlueHdi 110 S&S Feel Pack berlina con portón 81kW 5P manual
First Registrationdate:	15/09/2022	Fiscalpower:	
Expertise Mileage:	97345	Power Kw:	
Bodytype:	SUV	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total:	2	Central consol F
Number keys remote:	1	Luggage cover
GPS big screen color:		Rear parking sensors
Windows electric F:		
Windows electric R:		
Cruise Control:		
Steering wheel multifunctional:		
Steering wheel leather:		
Radio multimedia:		
Type of climate control:	Autom climate control	

Tyres

195/60/18/96 H				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/60 R 18 96 H
Tyre size FR				195/60 R 18 96 H
Tyre size RL				195/60 R 18 96 H
Tyre size RR				195/60 R 18 96 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit:	Yes
-------------	------------

Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FR, Dent(s), Repair and paint (complete)



Door RR, Dent(s), Paintless dent repair



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



