



Mercedes GLE-Klasse (KKL): 2CCP229

Vinnumber:	W1N1671541A706393	Versionname:	GLE350e Business Solution 2.0i 333k/cv 5p 4Matic 9G-Tronic
First Registrationdate:	3/06/2022	Fiscalpower:	
Expertise Mileage:	129192	Power Kw:	155
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	275/50/20/113 W			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				275/50 R 20 113 W
Tyre size FR				275/50 R 20 113 W
Tyre size RL				275/50 R 20 113 W
Tyre size RR				275/50 R 20 113 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	2		
Number of charging cables (rapid charge)	1		

Backrest cover FR, Tear, Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Wing trim RR, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Kenteken	2CCP229
Merk Model	Mercedes GLE350e Business Solution 2.0i 333k/cv 5p 4Matic 9G-Tronic
Brandstofsoort	Benzine
Datum deel1	6/3/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/10/26	124,298	diagnose	Uitvoeren
5/19/26	123,657	klein materiaal	
5/19/26	123,657	mercedes assyst a	Uitvoeren
5/19/26	123,657	ruitenwisserrubber vooraan	Vervangen
5/19/26	123,657	versnellingsbakolie	Vervangen
5/6/26	122,489	koelwatervloeistof	Bijvullen/-laden
11/6/25	106,489	diagnose	Uitvoeren
11/6/25	106,489	klein materiaal	
8/29/25	100,259	klein materiaal	
8/29/25	100,259	mercedes assyst b	Uitvoeren
8/29/25	100,259	trekhaak	Reinigen
3/21/25	89,562	klein materiaal	
3/21/25	89,562	ruitenwisser mechanisme	Vervangen
3/21/25	89,562	ruitenwisserrubber achter	Vervangen
3/21/25	89,562	ruitenwisserrubber vooraan	Vervangen
1/15/25	83,091	diagnose	Uitvoeren
9/6/24	74,428	bougie	Vervangen
9/6/24	74,428	klein materiaal	Uitvoeren
9/6/24	74,428	luchtfilter	Vervangen
9/6/24	74,428	mercedes assyst a	Uitvoeren
9/6/24	74,428	remvloeistof	Vervangen
5/27/24	66,332	koelwatervloeistof	Bijvullen/-laden
5/2/24	64,750	controle niveaus	Uitvoeren
1/15/24	54,944	ruitenwisser mechanisme	Repareren
12/8/23	49,906	klein materiaal	Uitvoeren
12/8/23	49,906	mercedes assyst b	Uitvoeren
12/8/23	49,906	trekhaak	Controleren
7/11/23	35,623	klein materiaal	Uitvoeren
7/11/23	35,623	ruitenwisserrubber vooraan	Vervangen
6/23/23	31,971	controle niveaus	Uitvoeren
4/17/23	25,350	klein materiaal	Uitvoeren
4/17/23	25,350	mercedes assyst a	Uitvoeren
3/27/23	21,477	controle niveaus	Uitvoeren