



Toyota Corolla: GRX21V

Vinnnumber:	SB1ZB3AEX0E131005	Versionname:	Corolla 1.8 Hybrid 103kW Active Touring Sports CVT
First Registrationdate:	19/11/2024	Fiscalpower:	
Expertise Mileage:	91236	Power Kw:	72
Bodytype:		Body colour	Night Sky Black metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	663
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Rear view camera
GPS		
Autom climate control		
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 16 / 91 / V / Aluminium	2,8 mm	Vredestein	All season
	Right	205 / 55 / 16 / 91 / V / Aluminium	3,2 mm	Vredestein	All season
Rear	Left	205 / 55 / 16 / 91 / V / Aluminium	5,0 mm	Vredestein	All season
	Right	205 / 55 / 16 / 91 / V / Aluminium	4,1 mm	Vredestein	All season

Assistance equipment

Number of charging cables (rapid charge)	0
--	----------

Service, Maintenance, Execute



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Roof, Scratch(es), Polish



Kenteken	GRX21V
Merk Model	Toyota Corolla 1.8 Hybrid 103kW Active Touring Sports
Brandstofsoort	Benzine
Datum deel1	19-11-24

Datum reparatie	Kilometerstand	Reparatie omschrijving
13-05-26	75.459	Onderhoudsbeurt
05-01-26	52.655	Onderhoudsbeurt
05-01-26	52.655	Ruitenwischerblad(en) voorzijde
05-01-26	52.655	Vervanging band
05-09-25	31.795	Onderhoudsbeurt
13-06-25	14.555	Onderhoudsbeurt
20-11-24	30	Vervanging band