MACADAM







## Ford Mustang Mach-E (KKL): 2CKJ729

| | | | |
|---|---|---|---|
| Vinnumber: | **WF0TK1E71NMA23578** | Versionname: | **Mach-E Extended Range 294pk/cv 5p RWD** |
| First Registrationdate: | **24/08/2022** | Fiscalpower: | |
| Expertise Mileage: | **198508** | Power Kw: | **69** |
| Bodytype: | | Type of rims (mounted) | **Aluminium** |
| Gearbox: | **Automatic** | | |
| Transmission: | | | |
| Fueltype: | **Electric** | | |
| Maintenance | **OK** | | |
| Battery functioning | **Yes** | | |
| Type of rims (mounted) | **Aluminium** | | |
| Certificate of Conformity | **Yes** | | |
| Category | **Passenger Car** | | |
| Registration Certificate Car (BE) | **Yes** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **2** | Luggage cover | |
| GPS | | Type of Tow bar | **No Tow bar** |
| Type of Maintenance book | **Digital maintenance** | | |
| Type of GPS storage | **HD** | | |

## Tyres

| | | | | |
|---|---|---|---|---|
| Summer tyres: | **225/60/18/104 W** | | | |
| | Fr.L. | **Vredestein: 4 mm** | Fr.R. | **Vredestein: 4 mm** |
| | Re.L. | **Vredestein: 4 mm** | Re.R. | **Vredestein: 4 mm** |

| | |
|---|---|
| Tyre profile depth FL | **4.0** |
| Tyre profile depth FR | **4.0** |
| Tyre profile depth RL | **4.0** |
| Tyre profile depth RR | **4.0** |
| Tyre size FL | **225/60 R 18 104 W** |
| Tyre size FR | **225/60 R 18 104 W** |
| Tyre size RL | **225/60 R 18 104 W** |
| Tyre size RR | **225/60 R 18 104 W** |
| Tyre type FL | **Summer** |
| Tyre type FR | **Summer** |
| Tyre type RL | **Summer** |
| Tyre type RR | **Summer** |
| Tyre make FL | **2480** |
| Tyre make FR | **2480** |
| Tyre make RL | **2480** |
| Tyre make RR | **2480** |

## Assistance equipment


| | | | |
|---|---|---|---|
| Repair kit | **Yes** | Compressor | **Yes** |
| Number of charging cables (normal) | **1** | | |
| Number of charging cables (rapid charge) | **1** | | |

## Seat cover FL, Worn, Acceptable





## Door panel RR, Scratch(es), Acceptable


Seat cover FR, Worn, Acceptable




Bumper F, Scratch(es), Acceptable




Bonnet, Scratch(es), Acceptable


Windscreen, Stone chip(s), Windscreen repair





Door FL, Dent(s), Acceptable




Door FL, Scratch(es), Spot repair




Door RL, Scratch(es), Acceptable




Door RL, Dent(s), Acceptable




Internal boot lining R, Broken, Replace





Tailgate / Boot, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable




Door FR, Scratch(es), Acceptable




| | |
|---|---|
| **Kenteken** | |
| **Merk Model** | |
| **Brandstofsoort** | |
| **Datum deel1** | |

| Datum reparatie | Kilometerstand | Reparatie omschrijving | Bewerking |
|---|---|---|---|
| | | | |