



PEUGEOT 5008

Vinnumber:	VF3M45GFRLS197588	Versionname:	1.6 PureTech 132kW S&S EAT8 GT Line
First Registrationdate:	14/09/2020	Fiscalpower:	
Expertise Mileage:	141402	Power Kw:	132
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1229
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	19300.0		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	3	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

225/55/18/96 V				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 18 96 V
Tyre size FR				225/55 R 18 96 V
Tyre size RL				225/55 R 18 96 V
Tyre size RR				225/55 R 18 96 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3455,90
Seat cover FL, Deformed / Strained, Acceptable	0,00



Seat cover RR, Stain, Cleaning

29,16



Seat cover FR, Stain, Cleaning

29,16



Bumper moulding F, Scratch(es), Replace

202,03



Bonnet, Dent(s) and scratch(es), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

204,21



Wing trim FL, Scratch(es), Replace

155,63



Door trim FL, Scratch(es), Acceptable

0,00



Door FL, Dent(s) and scratch(es), Repair and paint (complete)

445,79



Door RL, Dent(s) and scratch(es), Acceptable

0,00



Door trim RL, Scratch(es), Acceptable

0,00



Wing RL, Scratch(es), Acceptable

0,00



Step L, Dent(s) and scratch(es), Spot repair

148,33



Bumper R, Dent(s), Spot repair

148,33



Boot lid covering R, Scratch(es), Acceptable

0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Door RR, Dent(s) and scratch(es), Repair and paint (complete)	445,79
---	--------



Door FR, Dent(s), Acceptable	0,00
------------------------------	------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Step R, Dent(s) and scratch(es), Spot repair	148,33
--	--------



Roof, Hail damage, Paintless dent repair (hail)	1090,72
---	---------

