MACADAM










PEUGEOT PARTNER: FX-896-BS

Vinnumber:	**VR3EFYHYCLN544021**	Versionname:	**PEUGEOT PARTNER BHDI 100 S&S 100 S&S 1000KG STD ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**10/02/2021**	Fiscalpower:	
Expertise Mileage:	**80133**	Power Kw:	**75**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Front parking sensors	
GPS big screen color		Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**205/60/16/96 V**			
	Fr.L.	**Dunlop: 70%**	Fr.R.	**Dunlop: 75%**
	Re.L.	**Continental: 40%**	Re.R.	**Continental: 35%**

Tyre profile depth FL	**3.7**
Tyre profile depth FR	**3.3**
Tyre profile depth RL	**5.6**
Tyre profile depth RR	**5.8**
Tyre size FL	**205/60 R 16 96 V**
Tyre size FR	**205/60 R 16 96 V**
Tyre size RL	**205/60 R 16 96 V**
Tyre size RR	**205/60 R 16 96 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**257**
Tyre make FR	**257**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Remote ignition key, Missing, Repair/replace (lump sum)




Tyre FL, Out of tolerance, Replace




Tyre FR, Out of tolerance, Replace




Side wall RL, Scratch(es), Paint







Bumper F, Deformed / Strained, Repair and paint (complete)






Wing FR, Dent(s) and scratch(es), Repair and paint (complete)








Rubber seal for boot lid, Tear, Replace







Bumper R, Scratch(es), Repair and paint (complete)








Bodywork, Not original part, Remove lettering





ALPHABET

Historique Maintenance

Immatriculation: **FX-896-BS** Date de 1ère immatriculation: **10/02/2021**

Modèle: **Peugeot PARTNER BHDI 100 S&S 100 S&S 1000KG STD ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
15/06/2026	78.079	MPS AUTOMOBILES	DIVERS FREIN
			REVISION
			FILTRE CLIM RPLT
			FILTRE A AIR RPLT
			FILTRE A CARBURANT RPLT
			LIQUIDE DE REFROIDISSEMENT RPLT
			DIVERS VITRAGE
			DIVERS ECLAIRAGE
			RECYCLAGE
			VOLANT MOTEUR RPLT
			DISQUES PLAQUETTES AV RPLT
26/02/2026	73.944	CERQUEIRA	ANTIPOLLUTION
12/11/2025	71.126	GARAGE DIDEROT	POT CATALYTIQUE FAP RPLT
			LIQUIDE DE REFROIDISSEMENT RPLT
			DIVERS ELEC
			BATTERIE RPLT
30/07/2025	65.772	GARAGE DIDEROT	DIVERS FREIN
			LAMPE CODE AVD RPLT
			INJECTEUR ADBLUE RPLT
21/02/2025	59.160	CAO CONTROLE	CONTROLE TECHNIQUE
21/02/2025	59.146	BEL	LAMPE CODE AVD RPLT
			BALAIS ESSUIE GLACE AV
			RECYCLAGE
			REVISION
			PLAQUETTES AV RPLT
17/02/2025	58.802	CONTITRADE FRANCE	REMPLACEMENT PNEUS 4 SAISONS
19/09/2024	48.952	CONTITRADE FRANCE	REMPLACEMENT PNEUS 4 SAISONS
19/12/2023	38.651	BEL	FILTRE CLIM RPLT
			LIQUIDE DE FREIN
			FILTRE A AIR RPLT
			REVISION
			DISQUES PLAQUETTES AV RPLT

Historique Maintenance

Immatriculation: **FX-896-BS** Date de 1ère immatriculation: **10/02/2021**

Modèle: **Peugeot PARTNER BHDI 100 S&S 100 S&S 1000KG STD ASPHALT VU [4P] bvm 5-102CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
			BALAIS ESSUIE GLACE AV
			REVISION
21/07/2022	19.428	BEL	REVISION ET CLIM
			PLAQUETTES AV RPLT