



IDENTIFICATION VEHICLE

Driver name:
Make: KIA
Model / version: NIRO
Vin: KNACS81FGP5041470
Plate:
Mileage: 65874
First registration: 02/11/2022
Color: Interstellar

ADDITIONAL INFORMATION



Category:
Transmission:
Interior color: ?
Metallic paint: ?
Type of lining: ?
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✗
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

depuis 07.22

Keyless Start

lève-vitres av électrique avec commande à impulsions

rétroviseurs rabattables électrique

système de navigation

phares LED

réglage hauteur phares

capteur de pluie

système de chargement sans fil pour Smartphone

volant chauffant

bouton de démarrage

chauffage supplémentaire (PTC)

moules de protection latérale noir

rétroviseurs peints "High Glossy"

rétroviseurs avec clignotants intégrés

combiné instruments avec Display TFT

phares antibrouillard à LED

feux ar à diodes (LED)

équipement noir avec chrome

enjoliveurs des cadres de portes satin

Head Up Display

caméra av

vitres des portes ar, custodes et lunette ar teintées foncé (Privacy Glas)

rétroviseur int jour/nuit automatique

Smart Keyless-Entry

système d'assistance angle mort & collision (BCA)

câble de charge Type E/F

refroidissement alternatif

sièges av chauffants

rétroviseurs électrique et chauffants

hayon électrique

Plug-in

caméra de marche arrière

aide au parking av/ar	1580 cc (1,6 L) 69/77 kW (essence) / 62/83 kW (électrique)	6 vitesses DCT
radar av	SBW System E-Shift	205/60 R 16 .. H
6,5 J x 16 Alu	norme anti-pollution Euro 6	système de contrôle de la pression des pneus
système de gonflage des pneus	Type Europe + Australie	plaquettes de frein Type Europe
sidebag central	galerie de pavillon	GLS
2 couches métallisée		

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	1	Fast charging cables:	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer		?
Front right	5 mm			Summer		?
Rear left	5 mm			Summer		?
Rear right	5 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Luggage compartment cover	Missing
2	Bonnet	Scratch(es)
3	Grill frame	Broken
5	Door RR	Scratch(es)
6	Wing trim RR	Scratch(es)

Total: 5

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Bumper R	Scratch(es)	✓	✗	✗
7	Inner door sill RR	Scratch(es)	✓	✗	✗
8	Door FR	Scratch(es)	✓	✗	✗

Total: 3

DAMAGES DETAILS


1 - Luggage compartment cover - Missing



2 - Bonnet - Scratch(es)



3 - Grill frame - Broken



5 - Door RR - Scratch(es)




6 - Wing trim RR - Scratch(es)



4 - Bumper R - Scratch(es) - Renta®



7 - Inner door sill RR - Scratch(es) - Renta®



8 - Door FR - Scratch(es) - Renta®



SIGNATURE

Expert

16/07/2026 11:48