MACADAM








RENAULT Captur: 8461-MCT

Vinnumber:	**VF1RJB00669841551**	Versionname:	**evolution E-Tech híbrido 105 kW (145CV) todoterreno 107kW 5P automática**
First Registrationdate:	**14/12/2022**	Fiscalpower:	
Expertise Mileage:	**88129**	Power Kw:	
Bodytype:	**SUV**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Hybrid**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**215/60/17/96 H**			
	Fr.L.	**Goodyear: 5 mm**	Fr.R.	**Goodyear: 5 mm**
	Re.L.	**Continental: 5 mm**	Re.R.	**Continental: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**215/60 R 17 96 H**
Tyre size FR	**215/60 R 17 96 H**
Tyre size RL	**215/60 R 17 96 H**
Tyre size RR	**215/60 R 17 96 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Boot lid covering R, Scratch(es), Replace




Registration document, Missing, Repair/replace (lump sum)





Steering wheel, Worn, Acceptable




Headlight L, Scratch(es), Polish




Wing trim FL, Scratch(es), Paint




Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)




Wheel bolt cover RL, Broken, Replace




Bumper F, Scratch(es), Repair and paint (complete)






Wing trim RR, Scratch(es), Paint




Outside rear-view mirror housing R, Scratch(es), Acceptable




Wing trim FR, Scratch(es), Paint




Tailgate / Boot, Crack, Repair and paint (complete)





Tyres, No damage, Check






ALPHABET

Datos del vehículo

Marca	RENAULT	Matrícula	8461-MCT
Modelo	Captur	VIN	VF1RJB00669841551
Versión	evolution E-Tech híbrido 105 kW (145CV) todoterreno 107kW 5P automática		

Histórico

Fecha	Descripción	Kilómetros	Taller
03/11/2023	Puerta delantera derecha, Puerta trasera derecha, Paragolpes delantero, Matricula delantera, Bajos sin perdida de liquidos	23301	TALLER MARSI
16/02/2024	Revisión 1 año	29108	ROMICAR AUTO S.L.
22/05/2024	Pinchazo+Equilibrado	36585	NEUMATICOS 10S.L
17/02/2025	Rev. 60.000 kms	53817	ROMICAR AUTO S.L.
07/08/2025	Ecotasa - N2, Goodyear / 543289 215/60X17 GYEAR.EFFIG.PERF.96H, Sustitucion y kit de montaje	64000	AUTOLAVADO COSLADA S.L.
11/11/2025	Luneta trasera o Luna posterior	69705	RALARSA HOLDING S.L.
09/02/2026	Aceite motor - - - ALP EURO, Arandela / tapón cárter - CORTECO - Rec.Plat. EuroTaller - ACERO - Nueva, Bujía, Filtro aceite - PURFLUX - Rec.Plat. EuroTaller, Filtro aire - BOSCH - Rec.Plat. EuroTaller, Rellenar Anticongelante, Rellenar Líquido frenos, Rellenar Líquido lavaparabrisas, Serv inspección 4º año, Sustituir Bujía, Sustituir Filtro aire, Tasa de gestión de aceites usados	76274	LAST MILE REPAIR S.L.
25/06/2026	Aceite motor - - - ALP EURO, Arandela / tapón cárter - CORTECO - Rec.Plat. EuroTaller - ACERO - Nueva, Bujía - DENSO - Rec.Plat. EuroTaller, Filtro aceite, Filtro aire - BOSCH - Rec.Plat. EuroTaller, Importe de pago por uso, Rellenar niveles, Serv inspección 4º año, Sustituir Bujía, Sustituir Filtro aire, Sustituir Rellenar niveles, Tasa de gestión de aceites usados	84050	LAST MILE REPAIR S.L.
20/04/2026	Batería - VALUE+ - Nueva, Importe de pago por uso, Sustituir Batería, Verificar Diagnosis, Verificar Diagnosis y borrado de averias después de reparar	84436	MARBELLA MOTOR SPORT S.L.

Fecha	Descripción	Kilómetros	Taller