



DS 7: GP-589-KG

Vinnumber:	VR1JCYHZUPY540130	Versionname:	DS DS 7 BlueHdi 130 Automatique BASTILLE VP [5P] bva 8-130CH-7cv (SUV)
First Registrationdate:	8/06/2023	Fiscalpower:	
Expertise Mileage:	131647	Power Kw:	96
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Gold
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
Windows electric F		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Type of climate control	Autom climate control	Seat cover lining	Lining Other

Tyres

	225/55/18/102 V			
Winter tyres:	Fr.L.	Michelin: 85%	Fr.R.	Michelin: 85%
	Re.L.	Michelin: 50%	Re.R.	Michelin: 60%
Tyre profile depth FL				2.5
Tyre profile depth FR				2.5
Tyre profile depth RL				4.9
Tyre profile depth RR				4.2
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Seat cover FL, Burned, Replace



Floor mat F, Tear, Replace



Interior, Dirty, Cleaning



Interior covering B pillar L, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Acceptable



Tyre FR, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Door RL, Dent(s), Repair and paint (complete)



Door FL, Scratch(es), Paint



Bumper moulding F, Scratch(es), Paint



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Deformed / Strained, Repair and paint (complete)



Bumper R, Scratch(es), Replace



Bumper moulding RL, Scratch(es), Replace



Roof, Dent(s) and scratch(es), Repair and paint (complete)



Historique Maintenance

Immatriculation: GP-589-KG Date de 1ère immatriculation: 08/06/2023

Modèle: DS 7 BlueHDi 130 Automatique BASTILLE VP [5P] bva 8-130CH-7cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
24/02/2026	115.271	AUTOBERNARD ISERE	REVISION
31/10/2025	101.034	VOIRON DISTRIBUTION AUTOMOBILE	DISQUES PLAQUETTES AR RPLT
	0		ESSAI
08/09/2025	91.585	C.B.B.	ADBLUE
	0		BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
	0		REVISION
09/12/2024	64.004	C.B.B.	REVISION ET CLIM ET AIR ET CARBURANT
12/04/2024	30.357	LE MANS MOTORS	REVISION
	0		RECYCLAGE