MACADAM










Volkswagen Crafter: VXD70S

Vinnumber:	**WV1ZZZSY9P9064182**	Versionname:	**Crafter 35 2.0 TDI 103kW FWD GB L3H3 automaat**
First Registrationdate:	**28/08/2023**	Fiscalpower:	
Expertise Mileage:	**248705**	Power Kw:	**103**
Bodytype:		Body colour	**Candywit**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Diesel**	Parking lot	**1194**
Number of seats	**2**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
Manual climate control		Sliding door right-side	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 75 / 16 / 113 / R / Steel	3,0 mm	Continental	All season
	Right	205 / 75 / 16 / 113 / R / Steel	4,1 mm	Continental	All season
Rear	Left	205 / 75 / 16 / 113 / R / Steel	7,0 mm	Continental	All season
	Right	205 / 75 / 16 / 113 / R / Steel	7,1 mm	Continental	All season

Assistance equipment

Malfunction, Not functioning (well), Diagnosis



Interior, Dirty, Cleaning





Outside rear-view mirror housing L, Broken, Replace





Door FL, Dent(s) and scratch(es), Repair and paint (complete)










Windscreen, Crack, Replace

Bumper FM, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Smart repair




Door FR, Dent(s) and scratch(es), Repair and paint (complete)











Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)








Side bar R, Scratch(es), Replace




Sliding door R, Dent(s), Repair and paint (complete)







Wing FR, Dent(s), Repair and paint (complete)






Outside rear-view mirror housing R, Scratch(es), Replace




Side wall panel RL, Broken, Replace




Side wall panel RR, Broken, Replace




Bumper corner RL, Broken, Replace




Rear light R, Broken, Replace




Bodywork, Chemical polution, Polish






Onderhoudshistorie van: WV1ZZZSY9P9064182

ALPHABET

Kenteken	VXD70S
Merk Model	Volkswagen Crafter 35 2.0 TDI 103kW FWD GB L3H3 automaat
Brandstofsoort	Diesel
Datum deel1	8/28/23

Datum reparatie	Kilometerstand	Reparatie omschrijving
7/13/26	232,472	Inspuitcomputer
6/11/26	230,360	Distributie riem
6/11/26	230,360	Luchtfilter
6/11/26	230,360	Nokkenashuis
6/11/26	230,360	Onderhoudsbeurt
6/11/26	230,360	Remschijf + blokken voor
6/11/26	230,360	Waterpomp
4/21/26	217,660	Reparatie band(en)
3/3/26	217,655	APK
3/3/26	217,655	Onderhoudsbeurt
3/3/26	217,655	Remvloeistof
3/3/26	217,655	Ruitenwisserblad(en) voorzijde
3/3/26	217,655	Vervanging band
1/26/26	0	Thermostaat
11/20/25	210,808	Vervanging band
10/23/25	203,885	Gloeistift
10/23/25	203,885	Remblokken achterzijde
10/23/25	203,885	Remslijtage indicator
9/26/25	202,936	Brandstoffilter
9/26/25	202,936	Brandstofleiding
9/26/25	202,936	Brandstofpomp
9/26/25	202,936	Brandstoftoevoeging
9/26/25	202,936	Verstuiver
5/26/25	166,536	Multiriem inclusief spanner
5/26/25	166,536	Onderhoudsbeurt
5/26/25	166,536	Remblokken voorzijde
5/26/25	166,536	Ruitenwisserblad(en) voorzijde
5/26/25	166,536	Vervanging band
4/30/25	158,700	Reparatie band(en)
11/4/24	102,072	Brandstoffilter
11/4/24	102,072	Luchtfilter
11/4/24	102,072	Onderhoudsbeurt
11/4/24	102,072	Ruitenwisserblad(en) voorzijde
11/4/24	102,072	Vervanging band
9/25/24	92,540	Remblokken achterzijde
9/25/24	92,540	Remblokken voorzijde
4/22/24	55,666	Vervanging band
4/22/24	56,310	Onderhoudsbeurt
4/22/24	56,310	Ruitenwisserblad(en) voorzijde
1/18/24	1	Vervanging band