



Ford Kuga: 2

Vinnnumber:	WF0FXXWPMHMM77746	Versionname:	
First Registrationdate:	7/05/2021	Fiscalpower:	
Expertise Mileage:	181595	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1525
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Luggage cover:	
Seats F heated:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	Headlighting LED	Type of Tow bar:	Tow bar collapsible
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather and alcantara		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

225/60/18/104 W				
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/60 R 18 104 W
Tyre size FR				225/60 R 18 104 W
Tyre size RL				225/60 R 18 104 W
Tyre size RR				225/60 R 18 104 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		

Total cost ex VAT:	668,19
Interior, Worn, Acceptable:	0,00



Bonnet, Chemical polution, Repair and paint (complete) 487,44



Door RL, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Boot lid covering R, Scratch(es), Replace 180,75



Tailgate / Boot, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Door FR, Dent(s) and scratch(es), Acceptable 0,00



Roof, Dent(s) and scratch(es), Acceptable

0,00

