



Ford Kuga: 2ATK926

Vinnnumber:	WF0FXXWPMHMB27549	Versionname:	
First Registrationdate:	9/07/2021	Fiscalpower:	
Expertise Mileage:	149666	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front		
Fueltype:	Hybrid Petrol		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Central consol F	
Number keys remote	2	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Roof bar black	
Board Computer		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of radio	Multimedia		
Type of GPS storage	HD		

Tyres

	225/60/18/104 V			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/60 R 18 104 V
Tyre size FR				225/60 R 18 104 V
Tyre size RL				225/60 R 18 104 H
Tyre size RR				225/60 R 18 104 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				257
Tyre make FR				257
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1347,49
Bumper F, Scratch(es), Spot repair	127,11



Luggage compartment cover, Damaged, Replace

264,02



Boot lid covering R, Scratch(es), Replace

180,95




Door FR, Dent(s) and scratch(es), Spot repair

183,21



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)

242,20



Tyres, Out of tolerance, Check

0,00



Bodywork, Not original part, Sticker removal

350,00



Bodywork, Damaged, Acceptable

0,00



