MACADAM










Polestar 2: N714GP

Vinnumber:	**LPSVSECEKNL051855**	Versionname:	**Polestar 2 165kW/ 63kWh Single Motor Standard Range**
First Registrationdate:	**19/11/2021**	Fiscalpower:	
Expertise Mileage:	**81214**	Power Kw:	**165**
Bodytype:		Body colour	**Snow (metallic)**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**572**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Rear view camera	
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 102 / V / Aluminium	5,5 mm	Michelin	Summer
	Right	245 / 45 / 19 / 102 / V / Aluminium	5,3 mm	Michelin	Summer
Rear	Left	245 / 45 / 19 / 102 / V / Aluminium	5,4 mm	Michelin	Summer
	Right	245 / 45 / 19 / 102 / V / Aluminium	5,7 mm	Michelin	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Door FL, Bad repair, Repair and paint (complete)




Wing RL, Bad repair, Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)






Bonnet, Scratch(es), Polish






Door FR, Deformed / Strained, Replace and paint




Door RR, Dent(s) and scratch(es), Repair and paint (complete)







Wheel arch cover FR, Scratch(es), Replace




Boot lid covering R, Scratch(es), Replace




Tailgate / Boot, Scratch(es), Polish





Bumper R, Scratch(es), Repair and paint (complete)




Onderhoudshistorie van: LPSVSECEKNL051855

ALPHABET

Kenteken	N714GP
Merk Model	Polestar Polestar 2 165kW/ 63kWh Single Motor Standard Range
Brandstofsoort	Elektrisch
Datum deel1	11/19/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
2/10/26	71,035	APK
9/15/25	66,300	APK
9/15/25	66,300	Onderhoudsbeurt
9/15/25	66,300	Sleutelbatterij
6/23/25	62,215	Ruitenwisserblad(en) voorzijde
1/27/24	33,747	Onderhoudsbeurt
1/27/24	33,747	Remvloeistof
5/5/23	22,498	Reparatie band(en)