



Polestar 2:

Vinnnumber:	LPSVSEGEKNL072309	Versionname:	POLESTAR POLESTAR 2 Long Range Single Motor
First Registrationdate:	12/04/2022	Fiscalpower:	231PK 5d/p AUT (534EGPB0K119)
Expertise Mileage:	79712	Power Kw:	170
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2412
Fueltype:	Electric		
Maintenance:	OK		
Maintenance:	over 492 dagen		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Luggage cover:	
Seats F heated:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	Headlighting LED	Type of Tow bar:	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

	245/45/19/102 Y			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				5.0
Tyre profile depth RR				6.0
Tyre size FL				245/45 R 19 102 Y
Tyre size FR				245/45 R 19 102 Y
Tyre size RL				245/45 R 19 102 Y
Tyre size RR				245/45 R 19 102 Y
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				255
Tyre make FR				255
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	1		

Total cost ex VAT	974,29
GPS, Not functioning (well), Acceptable	0,00




Door panel FL, Stain, Cleaning

29,16



Seat cover FR, Stain, Cleaning

29,16



Alloy rim FL polished, Scratch(es), Replace

507,55



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

204,21



Bumper R, Scratch(es), Acceptable

0,00



Alloy rim RR polished, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21

