



DS 7 CROSSBACK: GB-773-FH

Vinnumber:	VR1J45GBUMY520604	Versionname:	DS DS 7 CROSSBACK E-TENSE 4x4 300 BASTILLE + VP [5P] bva 8-300CH-11cv (SUV)
First Registrationdate:	12/08/2021	Fiscalpower:	
Expertise Mileage:	153024	Power Kw:	221
Bodytype:	SUV	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		

Tyres

235/50/19/103 V				
Summer tyres:	Fr.L.	Michelin: 55%	Fr.R.	Michelin: 50%
	Re.L.	Michelin: 85%	Re.R.	Michelin: 100%
Tyre profile depth FL				4.5
Tyre profile depth FR				4.9
Tyre profile depth RL				2.5
Tyre profile depth RR				1.6
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key (no insert), Broken, Repair/replace (lump sum)



Interior, Stain, Cleaning



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RR, Out of tolerance, Replace



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RL, Out of tolerance, Replace



Wing trim FL, Scratch(es), Replace



Door FL, Dent(s), Repair and paint (complete)



Wing RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FR, Scratch(es), Replace



Bumper moulding F, Scratch(es), Replace



Bumper moulding F, Scratch(es), Replace



Bumper moulding FR, Scratch(es), Replace



Windscreen, Stone chip(s), Windscreen repair



Wing trim FR, Scratch(es), Replace



Wing RR, Dent(s), Repair and paint (complete)



Wing trim RR, Scratch(es), Replace



Door RR, Dent(s), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Luggage compartment cover, Tear, Repair/replace (lump sum)



Boot lid covering R, Scratch(es), Replace



Historique Maintenance

Immatriculation: **GB-773-FH** Date de 1ère immatriculation: **12/08/2021**

Modèle: **DS 7 CROSSBACK E-TENSE 4x4 300 BASTILLE + VP [5P] bva 8-300CH-11cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
11/03/2026	142.647	MIDI AUTO 29	DIVERS MOTEUR
30/06/2025	121.200	MIDI AUTO 29	FEU ARG RPLT
	0		BATTERIE RPLT
	0		LIQUIDE DE FREIN
	0		DIVERS CLIM
	0		REVISION
14/06/2024	93.293	MIDI AUTO 29	BOITIER D ALLUMAGE RPLT
	0		REVISION ET CLIM
	0		COURROIE ACCESSOIRES RPLT
	0		BALAIS ESSUIE GLACE AV AR
17/11/2023	75.320	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
25/05/2023	62.539	MIDI AUTO 29	BOITIER D ALLUMAGE RPLT
	0		FILTRE A AIR RPLT
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION
20/01/2023	52.128	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
22/07/2022	32.455	SA CAZES	BOITIER D ALLUMAGE RPLT
	0		REVISION ET CLIM