

» Overview

Order number: 1002394323
Order completed: 08.04.2026 10:08
Report number: 10375309
VIN: WVGZZZ5N4PM056219



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SUV
Make:	Volkswagen
Model:	Tiguan
Manufacturers and type code:	0603 / CLD
Date of first registration:	14.03.2023
Mileage:	53,365 km
Proof of mileage:	ReadOff
Exterior colour:	Kings Red Metallic
Roof colour:	Kings Red Metallic
Propulsion:	4 Wheel-drive
Fuel:	Diesel
Engine size (cc):	2,000 ccm
Performance:	147 kW (200 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining Alcantara
Interior colour:	Titanschwarz/Titanschwarz/Schwarz/ Stormgrey
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	

"Kapstadt" 8J x 20, Gray Metallic, Volkswagen R, AirStop® tires 235/45 R20
 12-V outlet in center console in rear and in luggage compartment
 2 LED reading lights in front and 2 in rear
 2 USB-C ports in the front, 1 USB-C charging socket on the center console in the rear
 3 head restraints in rear
 30-color ambient lighting
 3-point seat belt for center rear seat
 3-point seat belts in front with height adjustment and seat belt pretensioners
 3-point seat belts with seat belt pretensioners for the outer rear seats
 4 alloy wheels "Kapstadt" 8J x 20, Gray Metallic
 4-cylinder diesel engine 2.0 l
 4-cylinder diesel engine 2.0 l TDI, 147 kW
 7-speed automatic transmission or dual-clutch transmission DSG for four-wheel drive, note: PR family EDF
 Adaptive Chassis Control DCC incl. Driving Mode Selection
 Adaptive Cruise Control ACC stop & go incl. speed limiter
 Additional luggage compartment light, removable and usable as a flashlight
 Advanced high-beam control Dynamic Light Assist for LED matrix headlamps
 Air Care Climatronic 3 zone automatic climate control w/ allergen filter, enhanced air filter a. controls in rear
 AirStop® tires 235/45 R20
 Alternator 180 A
 Anti-theft alarm system with interior monitoring, backup horn and towing protection
 App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto
 Area View incl. rear view camera system
 Aspherical exterior mirror on driver side
 Auto-dimming interior rearview mirror
 Automatic headlight control with LED separate daytime running light and Coming Home and Leaving Home feature
 Automatically-heated washer nozzles in front
 Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h)
 Battery 380 A (68 Ah)
 Body-colored bumpers, black lower parts, Silver Gray center part in front, chrome elements in rear
 Bracket for first aid kit and warning triangle
 Business Premium package incl. navigation system
 Carpet mats in front and rear
 Carrier frequency 433.92 MHz-434.42 Mhz
 Center armrest in front
 Chrome trims on the side windows
 CO2 variant

Cornering light and poor weather light
 Dark Red LED rear combination lamps
 Decorative inserts "Barrel Craft" for dashboard and front door trim panels
 Digital radio reception DAB+
 Disc brakes in front
 Disc brakes in rear
 Diversity antenna for FM reception
 Door and side trim panel
 Driver alert system
 Driver+front passenger airbag with fr. passenger airbag deactivation, incl. knee airbag on driver+fr. passenger side
 Driving on the right
 Dual-clutch transmission DSG DQ381
 Dynamic headlight range control with dynamic cornering light
 Dynamic Road Sign Display
 Easy Open & Close - sensor controlled luggage compartment opening and closing with remote unlocking
 ECO function
 Electromechanical parking brake with Auto Hold function
 Electronic Stability Control w/ driver steering recommendation, ABS, ASR, EDL, EDTC and trailer stabilization
 Elimination of nameplate for engine designation on luggage compartment lid
 Elimination of overhead storage compartment
 Elimination of Tire Mobility Set
 Emergency call service; no registration required, service is activated upon delivery
 Emission standard EU6 AP
 Equipment options subset for Germany
 ergoActive seats in front
 ergoActive seats with height adjustment in front, adjustable seat and backrest angle, thigh support longit. sliding
 Exterior mirror housings painted in Silver
 Exterior mirrors, power-adjustable, folding and heated, w/ front passenger exterior mirror lowering function
 First aid kit, warning triangle and safety vest
 Folding trailer hitch, with electric release
 Four-wheel drive 4MOTION
 Front stabilizer bar
 Front-end underbody cladding incl. stone guard
 Fuel system for diesel engine
 Gearshift knob in leather
 Harman Kardon sound system, 8+1 speakers, 480 W total power output, digital 16-chan. amplifier, subwoofer
 Hatchback
 Headliner

Head-up display	Operating voltage 12 V
Heated (without wires) and infrared-reflecting windshield	Parking heater and ventilation with radio remote control and timer
Heated front and outer rear seats	Parking heater and ventilation with radio remote control and timer
Hill Descent Control	Part set without country-specific prescriptive standard
Illuminated front scuff plates, in aluminum	Pedestrian Monitoring
Illuminated molding between headlamps	Power-adjustable lumbar supports in front with massage feature
Illuminated vanity mirrors in sun visors	Premium comfort seats in front
Initial standard fuel filling	Preparation for We Connect and We Connect Plus
Inserts of front seats and outer rear seats in ArtVelours microfleece	Privacy glass for rear side windows and rear window
Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer	Proactive passenger protection system in combination with Front Assist and Side Assist
IQ.DRIVE assistance systems package incl. semi-automated vehicle assistance in a medical emergency Emergency Assist	Progressive steering
IQ.LIGHT - LED Matrix headlamps with LED sep. daytime running light, dynamic cornering light and dynamic turn signal	Protective side molding
ISOFIX anchorage points for mounting of 2 child seats on rear bench seat, also for i-Size child seats	Radiator grille
Keyless locking and starting system Keyless Access with SAFELOCK	Radio
Laminated safety glass windshield, heated (without wires) and infrared-reflecting	Rain sensor
Lane change system Side Assist	Rear bench seat asymm. split folding, longitudinally movable and folding with load-through hatch and center armrest
Leather-wrapped multi-function steering wheel, heated, with shift paddles	Rear fog lamp
LED license plate lighting	Rear shock absorption
Left-hand drive	Rear stabilizer bar
License plate carrier in front and rear (ECE)	Refrigerant R1234yf
Light unit in front footwell	Regional code " ECE " for radio
LongLife Service Regime	Remote unlocking for rear seat backrest
Luggage compartment cover	Right exterior mirror, convex
Luggage compartment floor adjustable in 2 heights	Roof rails, silver-anodized
Luggage net	Safety-optimized front head restraints, longitudinally and height adjustable
Manual in German (Germany)	Service indicator 30 000 km or 2 years (variable)
Mexico manufacturing sequence	Shock absorption in front
Mobile phone interface "Comfort" with inductive charging feature	Side airbags for outer seats of 2nd row of seats, incl. side airbags in front and curtain airbag system
Multi-color Digital Cockpit "Pro" selection of different info profiles possible	Special identification label for EC for M1 passenger vehicles
Multifunction camera	Sports equipment
Navigation system "Discover Pro" incl. Streaming & Internet	Standard battery/alternator capacity
Navigation system "Discover Pro" incl. Streaming & Internet	Standard climatic zones
No special edition	Standard curb weight range
No special purpose vehicle, standard equipment	Standard engine starter
Non-folding front passenger seat backrest	Standard paint coating
Non-smoker's package: Storage compartment and 12-V outlet in front	Standard pedal cluster
Not hot country	Start-stop system with regenerative braking
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Storage compartment with cover on dashboard
Operating permit, alteration	Styling elements on the power mirror switch, window regulator switches and door pulls
	Suspension range 06 installation control only, no requirement forecast

Textile luggage compartment trim
 Tilting and sliding panoramic sunroof with rear panoramic sunroof
 Tire Pressure Monitoring System
 Tires without specification of tire brand
 Tool kit
 Top package
 Trailer maneuvering system Trailer Assist incl. Park Assist and Park Distance Control
 Travel Assist, Lane Assist and Emergency Assist
 Trims for alloy wheels
 Two-tone horn
 Type approval country Germany
 Vehicle class differentiation -55N-
 Vehicles with special upgrade measures
 Voice control
 VWD model year change
 Warning lamp for washer fluid level
 Warning signal and warning lamp for front and rear seat belts not fastened
 Weight range 20 installation control only, no requirement forecast
 Wheel locks with extended theft protection
 Wheelbase
 Winter package, additionally with heated outer rear seats
 With additional transport protection measures
 Without activated carbon canister with SCR
 Without additional tires
 Without alternative drive system
 Without country code (no DVD player in vehicle)
 Without decals and emblems
 Without delivery equipment
 Without drawers under front seats
 Without electronic steering column lock
 Without fire extinguisher
 Without folding table on front seat backrest
 Without garage door opener
 Without headlamp washer system
 Without heat accumulator/auxiliary heater
 Without partition
 Without rear spoiler
 Without seat ventilation/massage seat
 Without second battery
 Without special body measures
 Without storage compartment package/box
 Without vehicle inlet

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Hankook	Front	Left	Summer	Aluminium	235/45 ZR 20 100 Y	7.0 mm
Hankook	Front	Right	Summer	Aluminium	235/45 ZR 20 100 Y	7.0 mm
Hankook	Rear	Left	Summer	Aluminium	235/45 ZR 20 100 Y	7.0 mm
Hankook	Rear	Right	Summer	Aluminium	235/45 ZR 20 100 Y	7.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 10.2030

Compressor present: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Roof liner	Dirty	Cleaning
2	Wing FR	Dent(s)	Paintless dent repair
3	Inner door sill RL	Scratch(es)	Polish
4	Bumper R	Scratch(es)	Polish

» Usage Damages

Nr	Location	Damage type	Repair type
1	Bonnet	Stone chip(s)	Acceptable

» Commercial devaluation

Known previous damages:	No
Previous damages detectable:	No
Repainting present:	No
Paint thickness measurement performed:	Yes - no abnormalities/deviations

PAINTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVGZZZ5N4PM056219

VIN checked and matches documentation

Vehicle condition:

Average general condition

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

No

Engine test carried out:

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4




Rear Right 3/4



Mileage



Tools



Sill outer L



Sill outer R



Chassis nr



Wheel FL



Wheel FR




Wheel RL




Wheel RR



Central console




Engine compartment




Documents




Interior arrangement



Registration Certificate



Towbar



History Maintenance

Assessment

- Vehicle Inspection Report -

Number: 10375309
From: 08.04.2026



Interior - front



Interior - rear



Tirefit expiration date




GPS/Radio


» Devaluation Damages

DEVALUATION FACTORS



1 - Roof liner - Dirty - Cleaning





2 - Wing FR - Dent(s) - Paintless dent repair



3 - Inner door sill RL - Scratch(es) - Polish



4 - Bumper R - Scratch(es) - Polish



USAGE DAMAGES

1 - Bonnet - Stone chip(s) - Acceptable

