MACADAM








CITROËN C5 Aircross: 5974-NGS

Vinnumber:	**VR7A4DGZ0SL035866**	Versionname:	**Citroen Plug-in Hybrid 225 e-EAT8 Max todoterreno 165kW 5P automática**
First Registrationdate:	**20/10/2025**	Fiscalpower:	
Expertise Mileage:	**25045**	Power Kw:	
Bodytype:	**SUV**	Body colour	**Dark Blue**
Gearbox:	**Automatic**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Plug-in hybrid**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**No**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Roof bar black	
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**225/55/18/102 V**			
	Fr.L.	**Michelin: 3 mm**	Fr.R.	**Michelin: 3 mm**
	Re.L.	**Michelin: 5 mm**	Re.R.	**Michelin: 5 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**225/55 R 18 102 V**
Tyre size FR	**225/55 R 18 102 V**
Tyre size RL	**225/55 R 18 102 V**
Tyre size RR	**225/55 R 18 102 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**1**		
Number of charging cables (rapid charge)	**0**		

Boot lid covering R, Scratch(es), Replace




MOT certificate, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)




Malfunction indicator, Blinking, Check




Interior, Dirty, Cleaning




Door FL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)




Door FR, Scratch(es), Repair and paint (complete)




Internal boot lining L, Scratch(es), Replace




Tyres, No damage, Check





