

Volkswagen e-Golf, Mar-20, 114,973 km



Memo



VIN	WVWZZZAUZLW914255
Initial registration	20-03-2020
Initial Dutch Registration	20-03-2020
European Type Approval	e1*2007/46*0623*44
Mileage reading / hour counter reading	114,973 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	1515 kg
Doors	5
Power capacity	100 kW
Emission code / Energy label	Z
Wheelbase	263
Loading space	
Load capacity	
RDW details	
Battery capacity	35.8 kWh
Range	230 km
Battery health	
Charging cables type	2
AC/DC	AC
Battery purchase/rent	Unknown
Taxation	VAT (Yellow number plate)
Colour	Black
Country of registration	The Netherlands
Origin	Lease
Indicative catalog price	

Accessories fitted to vehicles

	Adaptive cruise control		Central locking remote control		Alloy rims
	Adaptive power steering		Cruise control		Metallic paint
	ABS		Electronic Stability Program		Navigation
	Automatic air conditioning ECC		Electric windows front		Parking sensors rear
	Automatic interior mirror dimmer		Electric windows front + rear		Parking sensors front + rear
	Bluetooth telephone connection		LED lighting		Start immobiliser

Accessories fitted to vehicles (stated by offerer, conditionally)

- | | | |
|---|---|---|
| <ul style="list-style-type: none"> • Achteropk verkeer waarsch • AEB • Armsteun achter • Armsteun voor • Band.sp.contr.syst. • Bestuurdersairbag • Boordcomputer • Bots herkenning+activatie • Buitensp. elektr. + verw. • Comfortstoel(en) • Dakspoiler • Dimlichten aut. • EBD | <ul style="list-style-type: none"> • ESP • Forward Collision Warning • Hill hold functie • Hoofd airbag(s) a. • Hoofd airbag(s) v. • Hoofdsteunen actief • In delen neerkl. achterb. • Knie airbag(s) • LED achterlichten • LED dagrijverlichting • LED koplampen • Lederen stuurwiel • Lendesteunen (verstelb.) | <ul style="list-style-type: none"> • Lichtmetalen velgen 16" • Multifunctioneel stuur • Multimedia-voorbereiding • Oplaadmogelijkheid • Parkeersensor voor • Passagiersairbag • Sperdifferentieel • Stoel best. hoogte verst. • Stoel pass. hoogte verst. • Vermoeidheids herkenning • Verstelbaar stuur • Vervolgbotsing preventie • Zij airbag(s) v. |
|---|---|---|




Comments

No remarks


Vehicle state


MOT due date	05-06-2028	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	1	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location Owner	Wheel locks	Not present



Tyres

Rim size	17"		
Wheel	Brand	Type	Tread depth
Front wheel left	Continental	All Season tyre	5 mm
Front wheel right	Continental	All Season tyre	5 mm
Rear wheel left	Continental	All Season tyre	6 mm
Rear wheel right	Continental	All Season tyre	6 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection				
Incident		Component	Observations	
Unacceptable damage				
1		Head liner	dirt (interior)	
2		Contactsleutel	Missing part	
3		Bekl zitting v r	crack	
4		Stoelbekleding zitting a	dirt (interior)	
5		Front wing left	scratch(es)	
6		Wheel rim left-rear	scratch(es)	
7		Front door left	dent(s)	
8		Rear wing left	dent(s)	
9		Rear door left	dent(s)	
10		Wheel rim left-front	scratch(es)	
11		Engine bonnet	scratch(es)	
12		Front bumper	scratch(es)	

13		Front door right	scratch(es)
14		Wheel rim right-front	scratch(es)
15		Rear right rim	scratch(es)
16		Rear wing right	various damage (see photo)
17		Front door right	dent(s)
18		Front wing right	various damage (see photo)
19		Rear bumper	scratch(es)
Comments No remarks			

