



PEUGEOT 3008: GF-704-HK

Vinnumber:	VF3M4DGZUNS042610	Versionname:	PEUGEOT 3008 1.6 HYBRID 225 E-EAT8 Allure VP [5P] bva 8-225CH-10cv (SUV)
First Registrationdate:	21/03/2022	Fiscalpower:	
Expertise Mileage:	88563	Power Kw:	165
Bodytype:	SUV	Body colour:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	Lining Other
Type of climate control	Autom climate control		Lining Semi-leather

Tyres

225/55/18/102 V				
Summer tyres:	Fr.L.	Michelin: 70%	Fr.R.	Michelin: 90%
	Re.L.	Michelin: 80%	Re.R.	Michelin: 90%
Tyre profile depth FL				3.8
Tyre profile depth FR				2.0
Tyre profile depth RL				3.0
Tyre profile depth RR				2.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Seat cover FL, Tear, Replace



Interior, Dirty, Cleaning



Inner door sill RR, Dent(s) and scratch(es), Repair and paint (complete)



Tyre RL, Out of tolerance, Replace



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre RR, Out of tolerance, Replace



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door RL, Scratch(es), Polish



Door FL, Scratch(es), Paint



Wing trim RL, Unclasped, Dismount/Mount



Bumper moulding F, Scratch(es), Paint



Wing RR, Scratch(es), Paint



Charging cable (normal), Missing, Replace



Bumper corner RL, Scratch(es), Paint



Historique Maintenance

Immatriculation: **GF-704-HK**

Date de 1ère immatriculation: **21/03/2022**

Modèle: **Peugeot 3008 1.6 HYBRID 225 E-EAT8 Allure VP [5P] bva 8-225CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
08/06/2026	88.041	LE RELAIS DE LA FORGE	DIVERS MOTEUR
			REVISION
			FILTRE CLIM RPLT
			LIQUIDE DE FREIN
			BATTERIE RPLT
			FILTRE A AIR RPLT
			BOUGIES ALLUMAGE RPLT
			LIQUIDE DE REFROIDISSEMENT RPLT
01/06/2023	27.514	LE RELAIS DE LA FORGE	REVISION