



Expertise

Protocol number: 46670643
Order No. / Reference: 26646318
Inspection date: 23 Jul 2026

Manufacturer: Mercedes-Benz

Model: E 220 d 4Matic 9G-TRONIC Avantgarde

VIN: W1KLF0FB7SA105786



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz E 220 d 4Matic 9G-TRONIC Avantgarde	
Vehicle Identification number	W1KLF0FB7SA105786
Mileage (Read)	38,891 km
First registration	1 Oct 2024
Number of holders	1
Next periodical technical inspection	10/2027
(Report not on hand)	
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,993 ccm / 4
Power	145 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	Saloon car
Colour / colour code	Hightechsilber Metallic
Doors / Seats	4 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	53 Tag(e)
Last service on / at	09/2025 at 21,451 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HD788481
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	short drive on the company premises	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / BNH 00079		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,580 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102H	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	225/55 R18 102H	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R19 102Y	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	275/40 R19 105Y	Summer tyres on Light alloy	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS - Anti-lock braking system with electronic brake-force distribution (EBD)
- Airbag: Automatic passenger airbag deactivation
- Airbag: Center airbag
- Airbag: Windowbag for driver, front passenger and rear passengers
- 4MATIC all-wheel drive
- ATTENTION ASSIST
- Electrically folding exterior mirrors
- Tachometer
- Electronic Stability Program (ESP)
- Chassis: AGILITY CONTROL chassis with selective damping system and lowered suspension
- Pedestrian protection
- Transmission: 9-speed automatic, 9G-TRONIC
- Interior and exterior mirrors automatically dimming
- KEYLESS-GO with flush-mounted door handles
- Fuel tank with larger capacity
- LED High Performance Headlights
- Center console wood ash black open pore
- Package: AVANTGARDE Advanced
- Package: AVANTGARDE Interior
- Upholstery: ARTICO man-made leather/Ljusdal fabric
- Radio: MBUX multimedia system Premium
- Radio accessory: Communication module (5G) for using Mercedes me connect
- Tire pressure monitoring system (TPMS)
- Wheels: 45.7 cm (18") alloy wheels in a 5-spoke design
- Seats: Rear seat backrests foldable
- Lane Keeping Assist, active
- Phone accessories: Apple CarPlay
- Phone accessories: Smartphone integration
- TIREFIT
- Ambient lighting with projection of the brand logo
- Pre-installation for digital key handover
- Electronic immobilizer
- Decorative elements, wood, ash, black, open-pore
- Adaptive Highbeam Assist
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Airbag: Side airbag for driver and front passenger
- Active Distance Assist DISTRONIC
- Active Parking Assist with PARKTRONIC
- Ambient lighting plus
- Automatically dimming exterior and interior mirrors
- Diesel particulate filter
- Third brake light
- Driver display
- Electric windows (4-way)
- Rear seat belt status indicator in the instrument cluster
- Velour floor mats
- Heated rear window with timer
- Interior headliner in nevagrau fabric
- THERMATIC automatic climate control
- Paint finish: Metallic
- Mercedes-Benz emergency call system
- Navigation: MBUX Navigation Premium
- Package: AVANTGARDE Exterior
- Package: USB
- PRE-SAFE system
- Radio accessories: Digital radio (DAB)
- Radio accessories: Pre-installation for MBUX Entertainment
- Remote Services Premium
- Rear view camera
- Heated seats for driver and front passenger
- Phone accessory: Android Auto
- Phone accessories: Wireless charging system for mobile devices at the front
- Blind Spot Assist
- Traffic Sign Assistant
- High-visibility vest for drivers
- Central display with 14.4" screen diagonal



Extra equipment

- GUARD 360° Vehicle Protection Plus (Break-in and theft warning - Tow-away protection with visual and audible warning upon detection of a change in position - Audible alarm - Interior monitoring (triggers upon movement inside the vehicle) - Assistance with vehicle theft (theft assistance), free for 3 years after activation - Emergency key deactivation, free for 3 years after activation - Collision detection, free for 3 years after activation - GUARD 360° label on the front side windows)
- Radio accessories: Burmester surround sound system (4 exciters (body sound transducers), 2 each in the backrests of the front seats - Dolby Atmos technology, for compatible audio formats - 15 amplifier channels with a total system output of 730 watts - 17 premium speakers including speaker units in the headliner - sound personalization - seat function for sound optimization for individual seat rows - 3 sound profiles: Pure, 3D Sound, Individual - dynamic sound adjustment)
- Package: Driving Assistance Package Plus (Active Speed Limit Assist, Extended Automatic Restart on Motorways, Route-Based Speed Adaptation with Traffic Jam Function, Active Steering Assist, Active Emergency Stop Assist with SOS Function, Emergency Lane Function, Active Brake Assist, Turning and Intersection Function, Traffic Jam Emergency Braking Function, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist, Exit Warning Function, Pedestrian Warning Function in Zebra Crossing Areas)
- Package: Winter package (heated steering wheel - heated windshield washer system)
- Price reduction component
- Wheels: 48.3 cm (19") light alloy wheels in 10-spoke design (painted black and polished - with front axle 245/45 R19 on 8.5J x 19 ET35.5 and rear axle 275/40 R19 on 9.5J x 19 ET51)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Instrument panel	Indicator light (RDKS) - on - Diagnosed and repair if necessary
2	Interior	Interior - Broken / torn - Smart repair
3	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value

Wear and tear

No.	Component group	Description
1	Roof	Roof (Steinschlag mit kleiner Delle) - Stone chips - No deduction
2	Roof	Roof rail - left side - Stone chips - No deduction
3	Trim / covers	Door trim - rear right side - Scratch(es) - No deduction
4	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Für den montierten Radsatz wurde kein Nachweis erbracht.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Instrument panel: Indicator light (RDKS) - on - Diagnosed and repair if necessary



Damage 2: Interior: Interior - Broken / torn - Smart repair



Damage 2: Interior: Interior - Broken / torn - Smart repair



Damage 2: Interior: Interior - Broken / torn - Smart repair



Damage 2: Interior: Interior - Broken / torn - Smart repair




Damage 3: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 3: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Wear and tear 1: Roof: Roof (Steinschlag mit kleiner Delle) - Stone chips - No deduction



Wear and tear 2: Roof: Roof rail - left side - Stone chips - No deduction



Wear and tear 3: Trim / covers: Door trim - rear right side - Scratch(es) - No deduction



Wear and tear 4: Front bumper: Front bumper - Stone chips - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1KLF0FB7SA105786

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ E 220 d 4Matic 9G-TRONIC

Datum	KM-Stand	Beschreibung
10.09.2025	21.451	Regelwartungsdienst