

INSPECTION REPORT

End of contract

GENERAL INFO

File	312269
License plate	2BMM819
Vehicle identification number	WMW31BB0902S02890
Dossier	2021 117 093
Make	Mini Mini Clubm.One D 116 Aut.
Mileage	90740
First registration	14/01/2022
client availability date	06/05/2026
inspectionDate	20/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
198	Door Rear Right / Door Handle / Replace	N
72	Side View Mirror Left // Painting	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
117	Wing Rear Left / Trim / Replace	N
162	Roof // Painting	N
187	Wing Rear Right / Trim / Replace	N
225	Side View Mirror Right // Polish	Y
233	Wing Front right // Painting	Y
306	Rear Loading Door Right / Polish	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
536	Trunk Compartment / Cover Storage Tray / Replace	N

Damage Pictures



Trunk Compartment / Cover Storage Tray / Replace-missing



Roof // Painting-Chemical reaction



Tyre Rear Right // Replace-worn



Wing Rear Right / Trim / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rear Loading Door Right / Polish-scratch



Wing Rear Left / Trim / Replace-scratch



Door Front Left // Smart Repair Small-scratch




Side View Mirror Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Front right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch




Side View Mirror Right // Polish-scratch



Door Rear Right / Door Handle / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent