



Renault Trucks Master:

Vinnumber:	VF6VF000868232434	Versionname:	Master RT 3T5 2.3 dCi 110kW FWD L3H1 Red Edition
First Registrationdate:	22/04/2022	Fiscalpower:	Plancher automaat
Expertise Mileage:	194012	Power Kw:	110
Bodytype:		Body colour	Gris Kempenners
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Steel
Fueltype:	Diesel	Parking lot	1187
Number of seats	2		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
Manual climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 65 / 16 / 112 / R / Steel	4,5 mm	Goodyear	All season
	Right	225 / 65 / 16 / 112 / R / Steel	5,1 mm	Goodyear	All season
Rear	Left	225 / 65 / 16 / 112 / R / Steel	8,0 mm	Goodyear	All season
	Right	225 / 65 / 16 / 112 / R / Steel	7,8 mm	Goodyear	All season

Assistance equipment


Seat cover FL, Worn, Replace



Shutter / cover, Scratch(es), Replace



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Side bar L, Dent(s), Replace




Side wall RL, Crack, Repair and paint (complete)



Door trim FL, Scratch(es), Replace



Bumper F, Scratch(es), Smart repair



Bumper grille, Broken, Replace



Windscreen, Scratch(es), Replace



Side repeater L, Broken, Replace



Side repeater R, Broken, Replace



Bonnet, Dent(s), Repair and paint (complete)



Wheel arch cover RR, Dent(s) and scratch(es), Replace



Side bar R, Dent(s), Replace




Door trim FR, Missing, Replace



Fuel cap cover, Broken, Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)




Mirror side repeater R, Scratch(es), Replace




Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RR, Crack, Repair and paint (complete)



Side wall panel RL, Crack, Replace



Boot door panel RR, Crack, Repair and paint (complete)



Bumper corner RL, Broken, Repair and paint (complete)



Bumper corner RR, Deformed / Strained, Replace and paint

