

## 2-DKL-557


2-DKL-557 · ST-line 125pk 92kw mHEV M6 Clipper · 22 June 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-DKL-557	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0PXXGCHPPD60817
Model	Focus	Cylinder Capacity	999 <sup>cm<sup>3</sup></sup>
Model Versions	ST-line 125pk 92kw mHEV M6 Clipper	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	06-04-2023
Color	Silver	Odometer	93.323 <sup>km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Black
KW	92	Number Headrests	5

Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

## Tire Specifications

<b>Tire</b>	<b>Profile</b>	<b>Brand</b>	<b>Width</b>	<b>Aspect Ratio</b>	<b>Radial</b>	<b>Type</b>
Front Left	6 <sup>mm</sup>	Vredestein	215 <sup>mm</sup>	50 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Left	7 <sup>mm</sup>	Vredestein	215 <sup>mm</sup>	50 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Front Right	6 <sup>mm</sup>	Vredestein	215 <sup>mm</sup>	50 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Right	7 <sup>mm</sup>	Vredestein	215 <sup>mm</sup>	50 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Spare Tire Type	Compressor					

## Damages



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Left

Door-edge chipped

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Left

Small scratch(es)

Touch-up / Polish

No



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

small dents / small scratches

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Front

Damaged

Rim repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Rear

Damaged

Rim repair

No



Damage Part

Fender - Rear Right

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Frontdoor - Right

Damage Type

small dents / small scratches

Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Reardoor - Right

Damage Type

small dents / small scratches

Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Rear seat

Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No