MACADAM









Ford Transit Custom: VGT28S

Vinnumber:	**WF0YXXTTGYLC50642**	Versionname:	**Transit Custom 340 2.0 TDCi 96kW Trend L2H1 GB automaat**
First Registrationdate:	**1/09/2020**	Fiscalpower:	
Expertise Mileage:	**198550**	Power Kw:	**96**
Bodytype:		Body colour	**Frozen White**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Diesel**	Parking lot	**878**
Number of seats	**3**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Hook	
Manual climate control		Sliding door right-side	
Radio multimedia		Sliding door left-side	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 65 / 16 / 109 / T / Steel	6,0 mm	Goodyear	Summer
	Right	215 / 65 / 16 / 109 / T / Steel	4,1 mm	Goodyear	Summer
Rear	Left	215 / 65 / 16 / 109 / T / Steel	5,2 mm	Goodyear	Summer
	Right	215 / 65 / 16 / 109 / T / Steel	5,6 mm	Goodyear	Summer

Assistance equipment

Headrest, Missing, Replace



Sliding door L, Dent(s) and scratch(es), Repair and paint (complete)





Bumper F, Crack, Repair and paint (complete)






Side wall RR, Scratch(es), Repair and paint (complete)






Bodywork, Chemical polution, Polish





Roof, Rust, Repair and paint (complete)




Onderhoudshistorie van: WF0YXXTTGYLC50642

ALPHABET

Kenteken	VGT28S
Merk Model	Ford Transit Custom 340 2.0 TDCi 96kW Trend L2H1 GB automaat
Brandstofsoort	Diesel
Datum deel1	9/1/20

Datum reparatie	Kilometerstand	Reparatie omschrijving
8/20/26	193,484	Wiellager voor
6/15/26	190,001	Remblokken achterzijde
6/15/26	190,001	Remblokken voorzijde
9/22/25	164,453	Airco fluor vulling
9/22/25	164,453	APK
9/22/25	164,453	Brandstoffilter
9/22/25	164,453	Distributieriem met spanrol
9/22/25	164,453	Onderhoudsbeurt
9/22/25	164,453	Riem/ multiriem
9/22/25	164,453	Ruitenwisserblad(en) voorzijde
1/29/25	148,854	Accu
12/13/24	144,275	Remblokken voorzijde
7/5/24	128,243	APK
7/5/24	128,243	Onderhoudsbeurt
7/5/24	128,243	Remblokken achterzijde
7/5/24	128,243	Remslijtage indicator
7/5/24	128,243	Vervanging band
8/15/23	101,915	APK
8/15/23	101,915	Radiateur
8/15/23	101,915	Vervanging band
6/30/23	99,818	Remschijf + blokken voor
6/30/23	99,818	Remslijtage indicator
1/23/23	82,227	Controle beurt
1/3/23	81,371	Brandstoffilter
1/3/23	81,371	Onderhoudsbeurt
1/3/23	81,371	Remklauw(en) achterzijde
1/3/23	81,371	Remschijf + blokken achter
1/3/23	81,371	Remvloeistof
1/3/23	81,371	Ruitenwisserblad(en) voorzijde
1/3/23	81,371	Vervanging band
9/6/22	66,209	Remblokken voorzijde
9/6/22	66,209	Remslijtage indicator
7/4/22	0	Accu
11/16/21	40,685	Brandstoffilter
11/16/21	40,685	Onderhoudsbeurt