MACADAM










Skoda Superb: N428JR

Vinnumber:	**TMBJW9NP9M7080229**	Versionname:	**Superb 1.4 TSI PHEV 160kW Business Edition Plus combi DSG**
First Registrationdate:	**3/11/2021**	Fiscalpower:	
Expertise Mileage:	**162386**	Power Kw:	**115**
Bodytype:		Body colour	**Brilliant Silver metallic**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Hybrid Petrol**	Parking lot	**386**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Lining semi-leather	
GPS		Lining Alcantara	
Autom climate control		Rear parking sensors	
Radio multimedia		Hook	
		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 45 / 18 / 94 / W / Aluminium	3,8 mm	Goodyear	Summer
	Right	235 / 45 / 18 / 94 / W / Aluminium	6,5 mm	Goodyear	Summer
Rear	Left	235 / 45 / 18 / 94 / W / Aluminium	7,1 mm	Continental	Summer
	Right	235 / 45 / 18 / 94 / W / Aluminium	6,5 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Roof liner, Stain, Cleaning




Door RL, Scratch(es), Repair and paint (complete)





Outside rear-view mirror housing L, Scratch(es), Replace and paint




Windscreen, Stone chip(s), Windscreen repair




Wing RR, Scratch(es), Polish




Boot carpet, Dirty, Chemical cleaning



Boot lid covering R, Scratch(es), Replace




Bumper R, Scratch(es), Repair and paint (complete)






Onderhoudshistorie van: TMBJW9NP9M7080229

ALPHABET

Kenteken	N428JR
Merk Model	Skoda Superb 1.4 TSI PHEV 160kW Business Edition Plus combi DSG
Brandstofsoort	Benzine
Datum deel1	11/3/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
6/29/26	155,710	Onderhoudsbeurt
12/3/25	140,034	Onderhoudsbeurt
12/3/25	140,034	Ruitenwisserblad(en) achterzijde
12/3/25	140,034	Ruitenwisserblad(en) voorzijde
9/29/25	135,226	Airo vulling
9/29/25	135,226	APK
9/29/25	135,226	Module koelventilator
9/29/25	135,226	Vervanging band
5/6/25	123,746	Bougie
5/6/25	123,746	Onderhoudsbeurt
5/6/25	123,746	Remvloeistof
9/9/24	105,516	Luchtfilter
9/9/24	105,516	Onderhoudsbeurt
2/20/24	85,652	High Voltage lader aansluiting
2/9/24	85,665	Reparatie band(en)
1/19/24	83,433	Luchtfilter
1/19/24	83,433	Onderhoudsbeurt
12/20/23	81,164	Ruitenwisserblad(en) achterzijde
12/20/23	81,164	Ruitenwisserblad(en) voorzijde
9/13/23	71,186	Bougie
9/13/23	71,186	Onderhoudsbeurt
9/13/23	71,186	Vervanging band
7/26/23	64,686	Sleutelbatterij
3/30/23	50,961	Onderhoudsbeurt
3/30/23	50,961	Ruitenwisserblad(en) voorzijde
11/10/22	35,246	Onderhoudsbeurt
5/23/22	17,231	Onderhoudsbeurt