



Expertise

Protocol number: 46661723
Order No. / Reference: 26644686
Inspection date: 22 Jul 2026

Manufacturer: Mercedes-Benz
VIN: W1NKM5GB4PF035593

Model: GLC 300 e 4Matic 9G-TRONIC AMG Line Advanced



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLC 300 e 4Matic 9G-TRONIC AMG Line Advanced	
Vehicle Identification number	W1NKM5GB4PF035593
Mileage (Read)	121,118 km
First registration	24 May 2023
Number of holders	2
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,999 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Nautikblau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	246 Tag(e)
Last service on / at	02/2026 at 105,685 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS720300
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BLC 00021		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,840 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	255/55 R18 109H	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105W	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	255/50 R19 105W	Summer tyres on Light alloy	Continental	4 mm
	255/50 R19 107W	Summer tyres on Light alloy	Continental	4 mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Adaptive Highbeam Assist
- Airbag: Kneebag for driver
- Airbag: Windowbag
- Active Lane Keeping Assist
- Ambient lighting
- AMG floor mats
- AMG sports pedal assembly made of brushed stainless steel with black rubber studs
- ATTENTION ASSIST
- Basic services
- Roof rails made of glossy anodized aluminum
- Downhill Speed Regulation (DSR)
- EASY-PACK tailgate
- Electronic Stability Program (ESP)
- Chassis: Comfort chassis
- Transmission: 9G-TRONIC
- Rear window wiper/washer system
- Instrument panel and door sills in ARTICO man-made leather in black nappa look
- Charging cable for household socket, 5m, smooth
- Charging cable for wallbox and public charging station, 5m, smooth
- LED High Performance Headlights
- Steering: Sport direct steering
- Mercedes-Benz emergency call system
- Navigation accessories: Extended MBUX functions
- Otto particulate filter
- Package: AMG Line Advanced (for hybrid models)
- Package: Interior light
- Package: Parking package with reversing camera
- Package: Mirror Package
- Upholstery: ARTICO leatherette/MICROCUT microfiber
- Radio accessories: MBUX multimedia system
- Tire pressure loss warning
- Wheels: Summer tires
- Windscreen wipers with rain sensor
- Phone accessories: Wireless charging system for mobile devices
- Pre-installation for digital key handover
- Immobiliser
- Central display
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- 4MATIC all-wheel drive
- AMG front apron with sporty air intakes and chrome trim element
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Automatic passenger airbag deactivation
- Brake system with larger brake discs on the front axle
- Double cup holder
- Tachometer
- EASY-Pack: Cargo area cover
- Driver display
- Fingerprint scanner
- Rear window heated
- Interior headliner fabric crystal grey
- Climate: THERMATIC automatic climate control
- Radiator grille with Mercedes-Benz pattern and integrated Mercedes star
- Charging system: Alternating current charging system (AC charging) up to 11 kW (3-phase)
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Center console in high-gloss black
- Navigation: MBUX Navigation Premium
- Package: Storage
- Package: Chrome Interior Package
- Package: Boot Comfort Package
- Package: Seating comfort
- Package: USB package
- Radio accessories: Digital radio (DAB)
- Wheel arch trims in body color
- Remote and Charging Services Plus
- Wheel accessories: TIREFIT with tire inflator compressor
- Heated seats for driver and front passenger
- Phone accessories: Smartphone integration
- Cruise control
- High-visibility vest for drivers
- Heat-insulating dark tinted glass
- Central locking with remote control



Extra equipment

- Towbar with ESP trailer stabilization
- Paint finish: Metallic
- Package: AMG Line Premium Plus (electrically adjustable driver's seat with memory function - Blind Spot Assist - Illuminated door sills with "Mercedes-Benz" lettering - Traffic Sign Assist - Acoustic glass - KEYLESS-GO Comfort Package - DIGITAL LIGHT with projection function - Parking Package with 360° camera - MBUX Augmented Reality for navigation - Panoramic sliding sunroof - Head-up display - THERMOTRONIC automatic climate control - Burmester 3D surround sound system)
- Cargo net (This feature protects you from loose items in the luggage compartment. The cargo net is very easy to use. You can attach or remove it in just a few steps.)
- Decorative elements in diamond pattern, silver-grey
- Head-up display
- Charging system: DC on-board charger (60 kW) (For your optimal charging speed with up to 60 kW)
- Wheels: 48.3 cm (19") AMG light-alloy wheels in 5-spoke design in conjunction with Night Package (aerodynamically optimized, painted tantalum grey and polished - front axle 235/55 R19 on 8.0 J x 19 ET 32.5 and rear axle 255/50 R19 on 9.0 J x 19 ET 30)
- Wheels: Complete summer wheel sets fitted at the factory
- Wheels: Winter complete wheels M+S 4-way 45.7 cm (18") light alloy wheels in 5-spoke design (aerodynamically optimized, black painted and gloss-turned with front axle 235/60 R18 on 8.0 J x 18 ET 32.5 and rear axle 255/55 R18 on 9.0 J x 18 ET 30)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - dent(s) - Smooth repair work
2	Front axle	Axles / undercarriage - Malposition - Set / adjust
3	2nd wheel set	1 alloy rim - Scratched - Loss in value
4	Front bumper	Cover bumper - front - Deformed - Replace
5	2nd wheel set	Tyres - complete set (Sommerreifen einseitig abgefahren) - Rough engine running - Replace
6	Door - front left side	Door - Scratched - Paint
7	Rear bumper	Rear bumper - Scratched - Paint
8	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
9	Door - rear right side	Door - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Door - rear left side	Door edge - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.





Figure 39: Misc.




Damage 1: Door - front right side: Door - dent(s) - Smooth repair work



Damage 1: Door - front right side: Door - dent(s) - Smooth repair work




Damage 3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 3: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage 4: Front bumper: Cover bumper - front - Deformed - Replace



Damage 4: Front bumper: Cover bumper - front - Deformed - Replace



Damage 4: Front bumper: Cover bumper - front - Deformed - Replace



Damage 5: 2nd wheel set: Tyres - complete set (Sommerreifen einseitig abgefahren) - Rough engine running - Replace



Damage 5: 2nd wheel set: Tyres - complete set (Sommerreifen einseitig abgefahren) - Rough engine running - Replace



Damage 5: 2nd wheel set: Tyres - complete set (Sommerreifen einseitig abgefahren) - Rough engine running - Replace



Damage 5: 2nd wheel set: Tyres - complete set (Sommerreifen einseitig abgefahren) - Rough engine running - Replace



Damage 5: 2nd wheel set: Tyres - complete set (Sommerreifen einseitig abgefahren) - Rough engine running - Replace



Damage 5: 2nd wheel set: Tyres - complete set (Sommerreifen einseitig abgefahren) - Rough engine running - Replace




Damage 5: 2nd wheel set: Tyres - complete set (Sommerreifen einseitig abgefahren) - Rough engine running - Replace




Damage 5: 2nd wheel set: Tyres - complete set (Sommerreifen einseitig abgefahren) - Rough engine running - Replace




Damage 6: Door - front left side: Door - Scratched - Paint




Damage 6: Door - front left side: Door - Scratched - Paint



Damage 6: Door - front left side: Door - Scratched - Paint



Damage 6: Door - front left side: Door - Scratched - Paint



Damage 7: Rear bumper: Rear bumper - Scratched - Paint



Damage 7: Rear bumper: Rear bumper - Scratched - Paint




Damage 7: Rear bumper: Rear bumper - Scratched - Paint




Damage 7: Rear bumper: Rear bumper - Scratched - Paint



Damage 7: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 9: Door - rear right side: Door - Scratched - Paint



Damage 9: Door - rear right side: Door - Scratched - Paint




Damage 9: Door - rear right side: Door - Scratched - Paint



Damage 9: Door - rear right side: Door - Scratched - Paint



Wear and tear 1: Door - rear left side: Door edge - Scratched - No deduction



Wear and tear 1: Door - rear left side: Door edge - Scratched - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1NKM5GB4PF035593

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ GLC 300 e 4Matic 9G-TRONIC Avantgarde Advanced

Datum	KM-Stand	Beschreibung
19.02.2026	105.685	Regelwartungsdienst
14.05.2025	77.960	Regelwartungsdienst
28.08.2024	50.900	Regelwartungsdienst
16.01.2024	25.020	Regelwartungsdienst