MACADAM








BMW 5 Reeks (MKL): 2CGY966

Vinnumber:	**WBA11CG070CL14393**	Versionname:	**530e Touring (G31) 2.0i 292pk/cv 5p Aut.**
First Registrationdate:	**25/07/2022**	Fiscalpower:	
Expertise Mileage:	**99369**	Power Kw:	**135**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**245/45/18/100 H**			
	Fr.L.	**Goodyear: 7 mm**	Fr.R.	**Goodyear: 7 mm**
	Re.L.	**Goodyear: 7 mm**	Re.R.	**Goodyear: 7 mm**

Tyre profile depth FL	**7.0**
Tyre profile depth FR	**7.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**245/45 R 18 100 H**
Tyre size FR	**245/45 R 18 100 H**
Tyre size RL	**245/45 R 18 100 H**
Tyre size RR	**245/45 R 18 100 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**1**

Windscreen, Stone chip(s), Replace







Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bumper moulding F, Broken, Replace



Bonnet, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Charging cable (normal), Missing, Check



Boot carpet, Stain, Cleaning



Boot lid covering R, Scratch(es), Acceptable




Tailgate / Boot, Scratch(es), Acceptable





Bumper R, Scratch(es), Acceptable







Tyre FR, Tear, Replace




Alloy rim RR polished, Scratch(es), Acceptable




Wing RR, Dent(s), Acceptable




Door FR, Scratch(es), Acceptable




Mirror side repeater R, Broken, Replace




Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)




Bodywork, Paint measurement, Acceptable




Onderhoudshistorie van: WBA11CG070CL14393

ALPHABET

Kenteken	2CGY966
Merk Model	BMW 530e Touring (G31) 2.0i 292pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	7/25/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/16/25	73,486	klein materiaal	
12/16/25	73,486	motorsteun	Vervangen
11/18/25	70,006	batterij	Vervangen
11/18/25	70,006	BMW/MINI service standaard omvang	Uitvoeren
11/18/25	70,006	BMW/MINI service voertuig-check	Uitvoeren
11/18/25	70,006	bougie	Vervangen
11/18/25	70,006	klein materiaal	
11/18/25	70,006	remvloeistof	Vervangen
11/18/25	70,006	service luchtfilter	Uitvoeren
11/18/25	70,006	service microfilter	Uitvoeren
11/18/25	70,006	service motorolie	Uitvoeren
2/22/24	35,564	batterij	Vervangen
2/22/24	35,564	BMW/MINI service standaard omvang	Uitvoeren
2/22/24	35,564	klein materiaal	
2/22/24	35,564	service microfilter	Uitvoeren
2/22/24	35,564	service motorolie	Uitvoeren