



BMW 5 BERLINE:

Vinnumber:	WBA11BL080CH11002	Versionname:	518d 100kW Aut.
First Registrationdate:	21/04/2021	Fiscalpower:	
Expertise Mileage:	152157	Power Kw:	100
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2716
Fueltype:	Hybrid Diesel		
Maintenance:	OK		
Maintenance:	+ 3000 km		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Front parking sensors:	
Seats F heated:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

245/45/18/100 Y				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				245/45 R 18 100 Y
Tyre size FR				245/45 R 18 100 Y
Tyre size RL				245/45 R 18 100 Y
Tyre size RR				245/45 R 18 100 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal):	0
Number of charging cables (rapid charge):	0

Total cost ex VAT	266,06
Bumper F, Scratch(es), Acceptable	0,00



Alloy rim RL, Scratch(es), Repair and paint (complete)

133,03



Door RL, Scratch(es), Polish

0,00



Door FL, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Acceptable

0,00



Alloy rim RR, Scratch(es), Repair and paint (complete)

133,03

