MACADAM










PEUGEOT PARTNER: FG-258-YS

Vinnumber:	**VR3EFBHYBKJ591272**	Versionname:	**PEUGEOT PARTNER BHDI 100 S&S STANDARD 1000KG PREMIUM VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**13/06/2019**	Fiscalpower:	
Expertise Mileage:	**103687**	Power Kw:	**73**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**1**	Rear parking sensors	
Windows electric F		Sliding door right-side	
Type of climate control	**Manual climate control**	Rear view camera	
		Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**215/65/16/98 H**			
	Fr.L.	**Michelin: 35%**	Fr.R.	**Michelin: 40%**
	Re.L.	**Michelin: 60%**	Re.R.	**Michelin: 45%**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**5.6**
Tyre profile depth RL	**4.3**
Tyre profile depth RR	**5.2**
Tyre size FL	**215/65 R 16 98 H**
Tyre size FR	**215/65 R 16 98 H**
Tyre size RL	**215/65 R 16 98 H**
Tyre size RR	**215/65 R 16 98 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Seat cover FR, Burned, Replace






Seat cover FR, Stain, Cleaning




Malfunction indicator, Blinking, Check



Instrument panel cover, Not functioning (well), Check



Inner door sill FL, Scratch(es), Paint






Windscreen, Stone chip(s), Replace





Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)






Bumper F, Scratch(es), Repair and paint (complete)









Grille, Scratch(es), Replace







Side wall RR, Scratch(es), Paint





Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)





Door trim RR, Scratch(es), Replace





Outer sill R, Scratch(es), Paint






Door FR, Dent(s) and scratch(es), Repair and paint (complete)





ALPHABET

Historique Maintenance

Immatriculation: **FG-258-YS** Date de 1ère immatriculation: **13/06/2019**

Modèle: **Peugeot PARTNER BHDI 100 S&S STANDARD 1000KG PREMIUM VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
10/06/2025	86.915	EXCALBUR CONTROLE	CONTROLE TECHNIQUE
13/01/2025	79.914	GARAGE DU MOULIN SEPRA	DIVERS ECHAPPEMENT
	0		TELECHARGEMENT CALCULATEUR
	0		CAPTEURS DIVERS RPLT
	0		SONDE LAMBDA RPLT
	0		INJECTEUR ADBLUE RPLT
	0		DIAG
12/09/2024	74.422	GARAGE DU MOULIN SEPRA	REVISION
	0		BALAIS ESSUIE GLACE AV
02/07/2024	70.511	AUTO BILAN COZIC OLIVIER	CONTRE VISITE POLLUTION
09/08/2023	57.640	TRUJAS SAS	FILTRE CLIM RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
	0		REVISION
	0		FILTRE A AIR RPLT
	0		DIVERS CLIM
	0		PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
13/06/2023	55.964	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
28/10/2022	47.929	GARAGE DU MOULIN SEPRA	BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM ET AIR ET CARBURANT
14/03/2022	40.694	GARAGE DU MOULIN SEPRA	BATTERIE RPLT
30/07/2021	33.699	GARAGE RAVIER	FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
	0		REVISION
03/07/2020	18.113	GARAGE DU MOULIN SEPRA	BALAIS ESSUIE GLACE AV
	0		REVISION