

Vehicle details

VIN	ZARNASAS6 N3048788	Registration date	01/01/1900	Exterior Color	Unknown
Brand	ALFA ROMEO	Licence Plate		Odometer	42 168 km
Model	TONALE 1.6 130 DS Sprint FWD				

Inspection Details




Generic equipment

Removable element



Technical Document

Emergency compressor kit	✓	User manual	✓
Triangle	✓	Warranty booklet	✓
Safety vest	✓	Spare key	✓
Rear parcel shelf	✓	Key	✓
Fire extinguisher	✓	Certificate of conformity	✓
Refill emergency kit	✗	Title / License document	✓
		Service manual holder	✗

Tyres



Damages

1		Part	Refill emergency kit	Repair Time	-	Part Cost	-
		Position		- Repair Cost	-	Gross Cost	25.84€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity		- Paint cost	-	Depreciation	-
		Repair mode	Lumpsum replacement	Flat Rate	25.84€	Net Cost	25.84€
2		Part	Service manual holder	Repair Time	-	Part Cost	20.00€
		Position		- Repair Cost	-	Gross Cost	20.00€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity		- Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	20.00€

DEKRA Automotive Solutions

3		Part	Wing moulding	Repair Time	0.20	Part Cost	163.37€
		Position	Front left	Repair Cost	12.00€	Gross Cost	175.37€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	175.37€
		teinte pas correcte difference de peinture					
4		Part	Door sill	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
5		Part	Alloy wheel 18"	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
6		Part	Door	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
7		Part	Alloy wheel 18"	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
8		Part	Wing	Repair Time	-	Part Cost	-
		Position	Front left	Repair Cost	-	Gross Cost	180.00€
		Damages	Improper repair	Paint Time	1.80	Depreciation %	-
		Severity	-	Paint cost	180.00€	Depreciation	-
		Repair mode	Repair	Flat Rate	-	Net Cost	180.00€
		teinte pas correcte difference de peinture					

Comments

vehicule enneiger

Signatures

Signature Receiver

Signature Expert