



PEUGEOT 3008: 7732-LJM

Vinnumber:	VF3MCYHZRLS134132	Versionname:	1.5 BlueHDi 96kW (130CV) S&S Allure EAT8
First Registrationdate:	27/08/2020	Fiscalpower:	tototerreno 96kW 5P automática
Expertise Mileage:	110513	Power Kw:	
Bodytype:	SUV	Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
GPS big screen color		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	225/55/18/102 Y			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 2 mm	Re.R.	Continental: 2 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				225/55 R 18 102 Y
Tyre size FR				225/55 R 18 102 Y
Tyre size RL				225/55 R 18 102 Y
Tyre size RR				225/55 R 18 102 Y
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Boot lid covering R, Scratch(es), Acceptable



Interior, Dirty, Cleaning



Seat cover FL, Tear, Replace



User's manual, Missing, Repair/replace (lump sum)



Service book, Missing, Repair/replace (lump sum)



MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller

Datos del vehículo

Marca

Modelo

Versión

Matrícula

VIN

Histórico

Fecha	Descripción	Kilómetros	Taller