TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48526124
Order No. / Reference: 27245067
Inspection date: 4 Nov 2026

Manufacturer: Fiat	Model: e-Ducato L3H2 (110kWh
VIN: ZFA250003SG042898	





Vehicle details

Manufacturer / Type / Model / Equipment	
Fiat e-Ducato L3H2 (110kWh	
Vehicle Identification number	ZFA250003SG042898
Mileage (Read)	7,498 km
First registration	14 Aug 2025
Number of holders	1
Next periodical technical inspection	08/2028
(Report not on hand)	
Fuel type	Electric
Power	85 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Ducato Weiß Uni
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	17,502 km
Last service on / at	08/2026 at 7,331 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HG456067
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2424 / AAH 00055		
Emission standard	459/2012	**fine dust sticker**	
Permitted total weight	4,250 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/75 R16 121S	All-season tyres on Steel	Bridgestone	7mm / 7mm
2)	225/75 R16 121S	All-season tyres on Steel	Bridgestone	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	225/75 R16 121S C	Summer tyres on Steel	Nexen	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the roof
- Passenger side airbag for double passenger seat
- Exterior mirror - Standard (short mirror arm - for vehicle width up to 2200 mm)
- Third brake light
- Electronic Stability Control (ESP) (Crosswind Assist - Trailer Stability Control - Post Collision Braking - Rollover Prevention - Traction Control (ASR) - Hydraulic Brake Assist (HBA) - Hill Start Assist - Adaptive Load Control (LAC) (Adaptation of ABS, ASR and ESP functions to vehicle load))
- Front interior light
- Headrests (3) height adjustable
- Cooling compartment for 1.5-liter bottles
- Charging cable: Mode 3 charging cable
- Upholstery: Black seat cover with double stitching and padded headrest
- Indirect tire pressure monitoring system (TPMS)
- Wheels: 16" steel rims (rims 6JX16 - tires 215/75 R16C)
- Wheels: full-size spare wheel
- Reversing warning system (acoustic warning signal for pedestrians)
- Seat belts: Three-point seat belts in the front
- Seat: Center armrest and lumbar support for driver's seat
- Seats: Double passenger seat with folding table in the middle backrest
- Telematics Box Module (TBM)
- Warning tone and light for unfastened seat belts, front
- Immobiliser
- ABS with EBD
- Driver's side airbag
- Electrically adjustable/heated exterior mirrors
- Battery (95 Ah)
- Rear parking sensors
- electric window regulators
- Speed limiter 90 km/h
- Transmission: 1-speed direct drive
- cup holder
- Hooks for securing goods in the cargo area
- Glove compartment, passenger side, with lid
- Air conditioning (Autonomous single-zone air conditioning with pollen filter)
- Paint finish: Solid color paint
- Headlight range adjustment, manual
- Radio: 7" infotainment system with touchscreen + DAB (Apple CarPlay and Android Auto™ integration.)
- Tire repair kit Fix & Go
- Wheels: Spare wheel carrier
- Rear view camera
- electric power steering
- Safety kit (Emergency Brake Assist (Pedestrian and Cyclist Detection) - Lane Keeping Assist - Traffic Sign Recognition - Driver Fatigue Warning - Intelligent Speed Assist - Event Data Recorder (EDR) / Black Box)
- Smart tachograph
- Door interior trim with storage compartments (including 1.5-liter bottle holder and speaker housing)
- Central locking with remote control

Extra equipment

- rubber mat
- Rear doors glazed
- Cargo area lining with floor
- Package: "Visibility Plus" package (rain and light sensor - fog lights with static cornering lights - full LED headlights)
- Package: PREMIUM CAB PANEL VAN with glove compartment (10" Audio-NAV system with touchscreen + DAB + Apple CarPlay & Android Auto - Dual USB charging port on the dashboard - Leather steering wheel & gearshift lever - Keyless entry & go - Rearview camera - Center glove compartment (instead of cup holders) - Techno dashboard - Wireless smartphone charging station - Seat base trim)
- Heated rear windows
- Cargo area ventilation
- City Plus Package
- Package: "Worksite N1 and N2" package (Traction+ - All-weather tires - Full-size spare wheel - Spare wheel carrier)
- Package: Winter (heated driver's seat - heated windshield)
- Sliding door, side right, glazed
- Partition wall: steel, with window
- Winter tire conversion

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Navigation



Figure 15: Misc.




Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.