MACADAM











BMW X1 (UKL): 2AAJ660

Vinnumber:	**WBA31AD0605T07778**	Versionname:	**X1 (F48) 18d xDrive 2.0d 150pk/cv 5p**
First Registrationdate:	**1/02/2021**	Fiscalpower:	
Expertise Mileage:	**156510**	Power Kw:	**110**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**plus 4100 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/55/17/97 Y**			
	Fr.L.	**Pirelli: 4 mm**	Fr.R.	**Pirelli: 4 mm**
	Re.L.	**Pirelli: 5 mm**	Re.R.	**Pirelli: 5 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**225/55 R 17 97 Y**
Tyre size FR	**225/55 R 17 97 Y**
Tyre size RL	**225/55 R 17 97 Y**
Tyre size RR	**225/55 R 17 97 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**264**
Tyre make FR	**264**
Tyre make RL	**264**
Tyre make RR	**264**

Assistance equipment

Interior, Smell, Ozone treatment



Bonnet, Scratch(es), Acceptable




Outside rear-view mirror housing L, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable




Door RL, Scratch(es), Acceptable




Luggage compartment cover, Missing, Replace



Bumper R, Scratch(es), Acceptable




Sill trim R, Dent(s), Replace




Door FR, Scratch(es), Acceptable




Outer door handle FR, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Acceptable




Door RR, Repaired, Check




Door FR, Repaired, Check




Bodywork, Paint measurement, Check

