

» Overview

Order number: 1002396807
Order completed: 09.04.2026 14:22
Report number: 10392388
VIN: WVGZZZA1ZPV570505



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SUV
Make:	Volkswagen
Model:	T-Roc
Manufacturers and type code:	0603 / CMK
Date of first registration:	23.12.2022
Mileage:	30,368 km
Proof of mileage:	ReadOff
Exterior colour:	Deep Black Perleffekt
Roof colour:	Deep Black Perleffekt
Propulsion:	Front
Fuel:	Petrol
Engine size (cc):	1,000 ccm
Performance:	81 kW (111 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	3
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Manual 6-speed
Upholstery type:	Lining Alcantara
Interior colour:	Titanschwarz-Anthrazit/Titanschwarz/ Schwarz
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	Both
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	

2 LED reading lights in front and 2 in rear	Decorative inserts "Lava Stone Black" for dashboard, center console and front door trim panels
2 USB-C ports in the front, 2 USB-C charging sockets on the center console in the rear	Digital radio reception DAB+
3 head restraints in rear	Disc brakes in front
3-cylinder SI engine 1.0 l	Disc brakes in rear
3-cylinder SI engine 1.0 l TSI, 81 kW	Diversity antenna for FM reception
3-point seat belts in front with height adjustment and seat belt pretensioners	Door and side trim panel in foam film, insert in leatherette
3-point seat belts with seat belt pretensioners for the outer rear seats	Drawer under right front seat
4 alloy wheels "Valencia" 7J x 17, Galvano Gray	Driver alert system
4 all-season tires 215/55 R17	Driver and front passenger airbag with front passenger airbag deactivation
4 doors	Driving Mode Selection
6 speakers	Driving on the right
6-speed manual transmission	Dynamic headlight range control
Activated carbon canister (Evaporative Emission Control System (EVAP))	Dynamic Road Sign Display
Adaptive Cruise Control ACC incl. speed limiter	ECO function
Air Care Climatronic 2 zone automatic climate control with enhanced air filter with activated carbon	Electromechanical parking brake with Auto Hold function
Alternator 140 A	Electronic engine sound
App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto	Electronic immobilizer
Asymmetric split folding rear seat backrest, with center armrest	Electronic Stability Control w/ driver steering recommendation, ABS, ASR, EDL, EDTC and trailer stabilization
Auto-dimming interior rearview mirror	Elimination of cooling system of glove compartment
Automatic headlight control with LED separate daytime running light and exit and entry lighting	Elimination of nameplate for engine designation on luggage compartment lid
Automatically-heated washer nozzles in front	Emergency call service; no registration required, service is activated upon delivery
Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h)	Emission standard EU6 AP
Basic equipment variant	Equipment options subset for Germany
Battery 380 A (59 Ah) EFB+	Exterior mirror housings in roof color
Black headliner	Exterior mirrors, power-adjustable, folding, and heated, with memory feature
Body-colored door lower parts	Exterior mirrors: aspherical on driver side, convex on front passenger side
Brake pad wear indicator	First aid kit, warning triangle and safety vest
Bumpers in "R-Line" style	Front scuff plates with "R-Line" logo
Business package incl. navigation system "Discover Media"	Front seats with height adjustment, ergoActive driver seat with longitudinally adjustable thigh support
Carpet mats in front and rear	Front stabilizer bar
Carrier frequency 433.92 MHz-434.42 Mhz	Front-wheel drive
Center armrest in front	Fuel system for fuel-injected SI engine
Central locking system without SAFELOCK, with radio remote control and 2 remote control folding keys	Gearshift knob in leather
Chrome elements on rotary light switch, power mirror switch, window regulator switches; vents with chrome frames	Hatchback
Completely folding front passenger seat backrest	Heated front seats
Cornering light and poor weather light	Height-adjustable and removable luggage compartment floor
Curtain airbag system for front and rear passengers incl. side airbags in front	High-beam control Light Assist
Dark Red LED rear combination lamps	Hill start assist
	Illuminated vanity mirrors in sun visors



Assessment

- Vehicle Inspection Report -

Number: 10392388
From: 09.04.2026

Initial standard fuel filling	Regional code " ECE " for radio
Inserts of front seats and outer rear seats in ArtVelours microfleece	Retro-reflectors in all doors
Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer	R-line equipment
ISOFIX anchorage points (mounting fixture for 2 child seats on rear bench seat)	Safety-optimized front head restraints
Laminated safety glass windshield, heat-insulating	Service indicator 30 000 km or 2 years (variable)
Lane keeping system Lane Assist	Shock absorption in front
Leather-wrapped multi-function sports steering wheel with touch control	Silver-anodized roof rails
LED Plus headlamps with LED separate daytime running light	Single-tone horn
Left-hand drive	Smoker's package
Light unit in front footwell	Special identification label for EC for M1 passenger vehicles
LongLife Service Regime	Sports comfort seats in front
Lumbar supports in front, power- adjustable on driver side, massage feature on driver side	Sports suspension
Manual in German (Germany)	Standard battery/alternator capacity
Manual transmission MQ200_GA	Standard climatic zones
Mobile phone interface "Comfort" with inductive charging feature	Standard manufacturing sequence
Multi-color Digital Cockpit, selection of different info profiles possible	Standard paint coating
Multifunction camera	Standard rear axle
Navigation system "Discover Media" incl. Streaming & Internet	Standard wheel bolts
No special edition	Start-stop system with regenerative braking
No special purpose vehicle, standard equipment	Surround lighting with welcome light
Not hot country	Suspension range 13 installation control only, no requirement forecast
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Tailgate/trunk lid unlocking from outside
Operating permit, alteration	Tire Mobility Set: 12-volt compressor and tire sealant
Operating voltage 12 V	Tire Pressure Monitoring System
Park Assist with Park Distance Control	Tires without specification of tire brand
Part set without country-specific prescriptive standard	Tool kit
Pedals in brushed stainless steel	Transport protection film (minimum protection) with additional transport protection measures
Pedestrian Monitoring	Trims for alloy wheels
Power windows	Type approval country Germany
Preparation for We Connect and We Connect Plus	Vehicle class differentiation -2GA-
Privacy glass for rear side windows and rear window	Vehicle repurchase
Progressive steering	Vehicles with special upgrade measures
Radio	Voice control
Rain sensor	Warning lamp for washer fluid level
Rear exhaust tailpipe (standard)	Warning signal and warning lamp for front and rear seat belts not fastened
Rear floor panel module, type 7	Weight range 3 installation control only, no requirement forecast
Rear fog light on one side, back-up light on both sides	Wheelbase
Rear view camera system	White ambient lighting
Rear window wiper with intermittent control	Without additional front underbody guard
Refrigerant R1234yf	Without additional tires
	Without alternative drive system
	Without auxiliary heater/parking heater

Without charging cable
Without decals and emblems
Without electric motor (hybrid)
Without extended safety system
Without exterior ambient lighting
Without fire extinguisher
Without folding table on front seat backrest
Without headlamp washer system
Without heat accumulator/auxiliary heater
Without lane change assist
Without partition
Without preparation for two-way radio installation
Without rear stabilizer bar
Without roof insert (standard roof)
Without socket
Without special body measures
Without trailer hitch
Without vehicle inlet

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Michelin	Front	Left	All season	Aluminium	215/55 R 17 94 V	5.0 mm
Michelin	Front	Right	All season	Aluminium	215/55 R 17 94 V	5.0 mm
Michelin	Rear	Left	All season	Aluminium	215/55 R 17 94 V	6.0 mm
Michelin	Rear	Right	All season	Aluminium	215/55 R 17 94 V	6.0 mm

Permitted: Yes**Roadworthy:** Yes**SPARE/EMERGENCY TYRE & ACCESSORIES****Toolkit present:** Yes**Repair kit present:** Yes**Repair kit expiration date:** 08.2026**Compressor present:** Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Wing FL	Rust	Repair and paint (complete)
2	Wing FR	Rust	Repair and paint (complete)
3	Preparationtime metal painting	Paint preparation	Execute
4	Engine insulation	Tear	Replace

» Usage Damages

The vehicle shows signs of wear consistent with its age, mileage and purpose.

» Commercial devaluation

Known previous damages:	Yes
Previous damages detectable:	No
Repainting present:	Yes
Repainting professionally executed:	Yes
Paint thickness measurement performed:	Yes - with abnormalities/deviations

PAINTTHICKNESS MEASUREMENT RESULTS

Part	Paint (µm)
Paint thickness Door FL (µm)	169.0
Paint thickness Door RL (µm)	165.0
At least 3 measurements were carried out per component.	

» Notes On The Assessment**Details of the assignment and the scope of the assessment:**

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVGZZZA1ZPV570505

VIN checked and matches documentation

Vehicle condition:

Average general condition

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

No

Engine test carried out:

Yes

» Remarks

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4



Rear Right 3/4




Mileage



Tools



Sill outer L




Sill outer R




Chassis nr




Wheel FL



Wheel FR




Wheel RL




Wheel RR



Central console



Engine compartment



Documents



Interior arrangement



Registration Certificate



Paint thickness Door RL



Paint thickness Door FL



History Maintenance



Interior - front




Interior - rear



Tirefit expiration date



Underbody scan



GPS/Radio

» Devaluation Damages

DEVALUATION FACTORS

1 - Wing FL - Rust - Repair and paint (complete)

Comment

Lenksträger.



2 - Wing FR - Rust - Repair and paint (complete)

Comment

Lenksträger



3 - Preparationtime metal painting - Paint preparation - Execute

4 - Engine insulation - Tear - Replace

