

INSPECTION REPORT

End of contract

GENERAL INFO

File	315574
License plate	2FMH094
Vehicle identification number	WBA11EG0905000938
Dossier	2022349039
Make	BMW X1 sDrive 18d 100kW Aut
Mileage	128583
First registration	18/06/2024
client availability date	24/06/2026
inspectionDate	14/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
103	Door Rear Left // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
321	Wheel Alloy Rear Left // Repair	Y

Damage Pictures



Wheel Alloy Rear Left // Repair-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Door Rear Left // Painting-scratch + dent



Windshield // Repair-cracked



Front Bonnet / Insulation / Replace-tear