



## BMW 318: K943SJ

|                         |                          |                        |                              |
|-------------------------|--------------------------|------------------------|------------------------------|
| Vinnumber:              | <b>WBA71DZ080FK93078</b> | Versionname:           | <b>318iA 115kW touring</b>   |
| First Registrationdate: | <b>25/02/2021</b>        | Fiscalpower:           |                              |
| Expertise Mileage:      | <b>141719</b>            | Power Kw:              | <b>115</b>                   |
| Bodytype:               |                          | Body colour            | <b>Phytonicblau metallic</b> |
| Gearbox:                | <b>Automatic</b>         | Paint type             | <b>Metallic</b>              |
| Transmission:           |                          | Type of rims (mounted) | <b>Aluminium</b>             |
| Fueltype:               | <b>Petrol</b>            | Parking lot            | <b>655</b>                   |
| Number of seats         | <b>5</b>                 |                        |                              |
| Type of rims (mounted)  | <b>Aluminium</b>         |                        |                              |
| Maintenance needed      | <b>Yes</b>               |                        |                              |

## Options

|                       |          |                      |
|-----------------------|----------|----------------------|
| Number of keys total  | <b>2</b> | Lining leather       |
| GPS                   |          | Rear parking sensors |
| Autom climate control |          |                      |
| Radio multimedia      |          |                      |

## Tyres

| Location | Position | Measures                           | Depth  | Make        | Type   |
|----------|----------|------------------------------------|--------|-------------|--------|
| Front    | Left     | 225 / 50 / 17 / 94 / H / Aluminium | 6,0 mm | Bridgestone | Winter |
|          | Right    | 225 / 50 / 17 / 94 / H / Aluminium | 5,6 mm | Bridgestone | Winter |
| Rear     | Left     | 225 / 50 / 17 / 94 / H / Aluminium | 6,1 mm | Bridgestone | Winter |
|          | Right    | 225 / 50 / 17 / 94 / H / Aluminium | 6,2 mm | Bridgestone | Winter |


## Assistance equipment

|                                          |          |
|------------------------------------------|----------|
| Number of charging cables (rapid charge) | <b>0</b> |
|------------------------------------------|----------|

## Service, Maintenance, Execute



## Door RL, Dent(s) and scratch(es), Repair and paint (complete)



## Wing RL, Scratch(es), Repair and paint (complete)




Door FL, Dent(s) and scratch(es), Repair and paint (complete)




Outer sill L, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Hail damage, Paintless dent repair (hail)



Bumper moulding FR, Broken, Replace and paint



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)





Fuel cap cover, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Replace



Tailgate / Boot, Hail damage, Paintless dent repair (hail)



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Roof, Hail damage, Paintless dent repair (hail)



|                |                         |
|----------------|-------------------------|
| Kenteken       | K943SJ                  |
| Merk Model     | BMW 318iA 115kW touring |
| Brandstofsoort | Benzine                 |
| Datum deel1    | 25-02-21                |

| Datum reparatie | Kilometerstand | Reparatie omschrijving            |
|-----------------|----------------|-----------------------------------|
| 10-11-25        | 125.065        | Remschijf + blokken achter        |
| 10-11-25        | 125.065        | Remschijf + blokken voor          |
| 10-11-25        | 125.065        | Ruitenwischerblad(en) achterzijde |
| 10-11-25        | 125.065        | Ruitenwischerblad(en) voorzijde   |
| 10-11-25        | 125.065        | Vervanging band                   |
| 17-07-25        | 116.080        | Sleutelbatterij                   |
| 21-01-25        | 98.435         | APK                               |
| 21-01-25        | 98.435         | Olie service                      |
| 21-01-25        | 98.435         | Ruitenwischerblad(en) achterzijde |
| 21-01-25        | 98.435         | Ruitenwischerblad(en) voorzijde   |
| 21-01-25        | 98.435         | Sleutelbatterij                   |
| 21-03-24        | 82.391         | Remvloeistof                      |
| 07-09-23        | 66.676         | Bougie                            |
| 07-09-23        | 66.676         | Luchtfilter                       |
| 07-09-23        | 66.676         | Olie service                      |
| 07-09-23        | 66.676         | Onderhoudsbeurt                   |
| 07-09-23        | 66.676         | Remblokken achterzijde            |
| 08-06-23        | 60.136         | Sleutelbatterij                   |
| 11-07-22        | 32.906         | Olie service                      |
| 11-07-22        | 32.906         | Sleutelbatterij                   |