

INSPECTION REPORT


End of contract

GENERAL INFO

File	312276
License plate	2CCY402
Vehicle identification number	WBA31AC0005V43649
Dossier	2021307136
Make	BMW X1 sDrive 16d 85kW Aut.
Mileage	73202
First registration	09/06/2022
client availability date	06/05/2026
inspectionDate	18/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
67	Wing Front Left / Trim / Replace	N
18	Bumper Front / Spoiler / Replace	N
32	Front Bonnet // Painting	Y
83	Door Front Left // Painting	Y
104	Door Rear Left // Repair & Painting	N
134	Bumper Rear // Repair & Painting	N
163	Roof // Repair & Painting	N
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	N
540	Interior // Repair 1	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N


Damage Pictures



Door Rear Right // Painting-scratch




Bumper Front / Spoiler / Replace-scratch




Door Rear Left // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent




Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Right // Smart Repair Small-scratch + dent



Interior // Repair 1-Incinerated



Roof // Repair & Painting-Chemical reaction



Front Bonnet // Painting-Chemical reaction



Interior Cleaning // Small-stain



Door Front Left // Painting-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front // Smart Repair Medium-scratch