



Ford Mustang: L666GS

| | | | |
|-------------------------|--------------------------|-------------------------|---|
| Vinnumber: | WF0TK1EM3MMA15843 | Versionname: | Mustang Mach-E 190kW/ 75,7kWh RWD automaat |
| First Registrationdate: | 20/05/2021 | Fiscalpower: | |
| Expertise Mileage: | 113274 | Power Kw: | 190 |
| Bodytype: | | Body colour: | Trendy Metaallak: Infinity Blue |
| Gearbox: | Automatic | Paint type: | Metallic |
| Transmission: | | Type of rims (mounted): | Aluminium |
| Fueltype: | Electric | Parking lot: | 1157 |
| Number of seats: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Maintenance needed: | No | | |

Options

| | | |
|-----------------------|----------|----------------------|
| Number of keys total | 2 | Lining leather |
| GPS | | Rear parking sensors |
| Autom climate control | | |
| Radio multimedia | | |

Tyres

| Location | Position | Measures | Depth | Make | Type |
|----------|----------|-------------------------------------|--------|-------------|--------|
| Front | Left | 225 / 60 / 18 / 104 / V / Aluminium | 6,2 mm | Bridgestone | Winter |
| | Right | 225 / 60 / 18 / 104 / V / Aluminium | 6,5 mm | Bridgestone | Winter |
| Rear | Left | 225 / 60 / 18 / 104 / V / Aluminium | 6,0 mm | Bridgestone | Winter |
| | Right | 225 / 60 / 18 / 104 / V / Aluminium | 5,3 mm | Bridgestone | Winter |


Assistance equipment

| | |
|--|----------|
| Number of charging cables (normal) | 1 |
| Number of charging cables (rapid charge) | 1 |

Interior, Dirty, Cleaning



Wing FL, Dent(s), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



| | |
|-----------------------|--|
| Kenteken | L666GS |
| Merk Model | Ford Mustang Mach-E 198kW/ 75,7kWh RWD automatisch |
| Brandstofsoort | Elektrisch |
| Datum deel1 | 20-05-21 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|-----------------|----------------|-----------------------------------|
| 25-07-25 | 89.758 | Remklauw(en) achterzijde |
| 23-06-25 | 88.206 | Airo vulling |
| 23-06-25 | 88.206 | Onderhoudsbeurt |
| 23-06-25 | 88.206 | Remvloeistof |
| 23-06-25 | 88.206 | Ruitenwischerblad(en) achterzijde |
| 23-06-25 | 88.206 | Ruitenwischerblad(en) voorzijde |
| 19-05-25 | 86.650 | APK |
| 23-05-22 | 19.462 | Reparatie band(en) |