



IDENTIFICATION VEHICLE

Driver name:
Make: NISSAN
Model / version: MICRA
Vin: VNVK1400469961826
Plate:
Mileage: 46320
First registration: 04/01/2023
Color:


ADDITIONAL INFORMATION




Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 2
Original key: ✓

PICTURES





VIN INFORMATION

EQUIPMENT

Board computer:	☐	Central locking:	☐
Compressor:	☒	Cruise control:	☐
Gps:	☐	Power steering:	☐
Rear parking sensor:	☐	Repair kit:	☒
Front seats heated:	☐	Steering wheel:	☐
Electric windows:	☐	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			All-seasons		☐
Front right	5 mm			All-seasons		☐
Rear left	5 mm			All-seasons		☐
Rear right	5 mm			All-seasons		☐

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot cover	Grooved
2	Seat cover FR	Stain
4	Door FL	Grooved
5	Wing RL	Dent(s) and scratch(es)
6	Bumper R	Grooved
7	Wing RR	Dent(s) and scratch(es)
8	Door RR	Dent(s) and scratch(es)
9	Wing FR	Dent(s) and scratch(es)
10	Door FR	Dent(s) and scratch(es)

Total: 9

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
3	Bodywork	Dent(s) and scratch(es)	✓	✗	✗


Total: 1

DAMAGES DETAILS

1 - Boot cover - Grooved




2 - Seat cover FR - Stain



4 - Door FL - Grooved




5 - Wing RL - Dent(s) and scratch(es)



6 - Bumper R - Grooved



7 - Wing RR - Dent(s) and scratch(es)



8 - Door RR - Dent(s) and scratch(es)



9 - Wing FR - Dent(s) and scratch(es)



10 - Door FR - Dent(s) and scratch(es)



3 - Bodywork - Dent(s) and scratch(es) - Renta®



