

## AUDI RS Q8

Vehicle reference:

**WUAZZZF19PD008752**

Body type:

Hatchback

Gearbox type:

Automatic

Engine size:

3996 cm<sup>3</sup>

Hybrid vehicle:

Electric, Petrol

Combustion engine power:

441 kW / 600 hp

Drive:

AWD

## Quick Check


### Damage


This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.


### Import


Vehicle imported

## Legend

 No issues reported or indicated

 Valuable Information

 Requires attention

 Data unavailable

## Extra information

### French history check BETA

Check if this vehicle has any history in France. You need to be the owner of this vehicle or be authorized by its owner to perform the check. Additional French history reports are provided in French and are available free of charge for all vehicles ever registered in France.


Check  
online  
version

# Damage Overview

01/2024

## Affected area (1):

Location reference, does not indicate the extent of the damage.



Reported in  
Germany

Damage type/cause  
Not available

## Estimated repair cost:


€ 500 - € 750

This is a rough estimate and the actual repair cost may be higher or lower. It does not show whether the damage has already been repaired. Prices are based on local rates and can vary between countries.

06/2024

## Affected area (3):

Location reference, does not indicate the extent of the damage.



Reported in  
Italy

Damage type/cause  
Not available

## Damage severity:



Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

## Damage Glossary

### Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.


### CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

# Owners BETA



## Owner(s) abroad

Purchase year: **2023**

Damage reported on: **01/2024**



## Owner(s) in Italy

Purchase year: **2024**

Damage reported on: **06/2024**

# History information

Date

Mileage

Event

2023-02-15

**First registration abroad**

01/2024

**Damage reported in Germany**

2024-04-19

**Imported to Italy**  
Registered in Italy

06/2024

**Damage reported in Italy**

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

## Technical details

### Engine and performance

**Hybrid vehicle**

Electric, Petrol

**Combustion engine power**

441 kW / 600 hp

**Electric engine power**

Not available

**Total system power**

Not available

### Other information

**EU standard code**

e1\*01/116\*0367

**Number of doors**

5

# CARFAX Glossary

## Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

## Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

## Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

## Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

## Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

## Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

# How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions](#).