MACADAM









VOLVO V60: GW-535-EC

Vinnumber:	**YV1ZWK7V6R2630104**	Versionname:	**VOLVO V60 B3 163 DCT 7 Start VP [5P] bva 7-163CH-9cv (break)**
First Registrationdate:	**3/04/2024**	Fiscalpower:	
Expertise Mileage:	**160148**	Power Kw:	**120**
Bodytype:	**Break**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Light Beige**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Type of climate control	**Autom climate control**	Rear view camera	
		Seat cover lining	**Lining Leather**

Tyres

Summer tyres:	**225/50/17/98 V**			
	Fr.L.	**Michelin: 60%**	Fr.R.	**Michelin: 55%**
	Re.L.	**Firestone: 25%**	Re.R.	**Firestone: 25%**

Tyre profile depth FL	**4.3**
Tyre profile depth FR	**4.6**
Tyre profile depth RL	**6.6**
Tyre profile depth RR	**6.4**
Tyre size FL	**225/50 R 17 98 V**
Tyre size FR	**225/50 R 17 98 V**
Tyre size RL	**225/50 R 17 98 V**
Tyre size RR	**225/50 R 17 98 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**258**
Tyre make RR	**258**

Assistance equipment

Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)







Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)







Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)







Bumper F, Deformed / Strained, Repair and paint (complete)





Bumper grille, Scratch(es), Acceptable




ALPHABET

Historique Maintenance

Immatriculation: **GW-535-EC** Date de 1ère immatriculation: **03/04/2024**

Modèle: **Volvo V60 B3 163 DCT 7 Start VP [5P] bva 7-163CH-9cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
07/10/2026	152.000	SOC REPAR AUTO ALIZON FRERES	BATTERIE RPLT
06/07/2026	151.803	AMPLITUDE AUTOMOBILES ST GEORGES DES COTEAUX	BOBINE ALLUMAGE RPLT
			DIAG
			REVISION ET CLIM
			LIQUIDE DE FREIN
11/03/2026	126.911	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
			PERMUTATIONS PNEUS
			REMPLACEMENT PNEUS HIVER
09/02/2026	120.633	BARBIER AUTOMOBILES	COURROIE ACCESSOIRES RPLT
			BALAI ESSUIE GLACE AR
			REVISION ET CLIM ET AIR ET BOUGIES
			HUILE BV RPLT
11/12/2025	109.174	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
			PERMUTATIONS PNEUS
14/08/2025	87.578	BARBIER AUTOMOBILES	REVISION ET CLIM
			BALAIS ESSUIE GLACE AV
11/04/2025	67.249	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
			PERMUTATIONS PNEUS
10/03/2025	60.253	BARBIER AUTOMOBILES	HUILE BV RPLT
			REVISION ET CLIM ET AIR ET BOUGIES
28/10/2024	33.030	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
			REMPLACEMENT PNEUS HIVER
16/10/2024	31.649	BARBIER AUTOMOBILES	REVISION ET CLIM