


Vehicle details

VIN	TMBJC7NYX NF028542	Brand	SKODA	Maintenance date	-
Licence Plate		Model	Enyaq iV 80 5d	Maintenance mileage	-
Registration date	28/12/2021	Year	2021	Exterior Color	White Solid
Odometer	152 325 km	Engine size	-	Interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	20/07/2026	Inspection loc.	
-----------------	------------	-----------------	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Load cover	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 235/55/19 Summer 6.0 mm



Continental 235/55/19 Summer 5.5 mm



Continental 235/55/19 Summer 5.0 mm



Continental 235/55/19 Summer 5.0 mm

Exterior

1



Part	Other bodywork
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	For info
	sticker resten

3




Part	Door
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

5



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	Repair

6



Part	Roof post A/B/C
Position	Left
Damages	Dented
Severity	-
Repair mode	Repair

7



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

9



Part	Fuel filler flap
Position	Back right
Damages	Broken
Severity	-
Repair mode	Replace

10



Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair


11



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair


Interior damage

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

4



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

8



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	For info